

Not Authored
& Foot

Trans-cab Auto Services Pte Ltd

AAD2407-078

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9926D

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 AUG 2024

SHD9926D

JTDKB3FU503092557

200303878K

TOYOTA

PRIUS GEN 4

13/7/2024

SML8900H/CHINA

6/11/2020

PART		LIST	
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,634.33 X
1	GLASS SUB-ASSY, REAR DOOR, LH	\$	518.07 X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	243.81 X
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	123.06 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	369.60 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	109.62 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	124.74 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	27.62 X
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	44.00 X
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	19.43 X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	756.74 X
1	COVER, REAR BUMPER	\$	612.68 X
1	RETAINER, REAR BUMPER SIDE, LH	\$	167.48 X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	428.19 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	329.49 X
1	COVER, REAR COMBINATION LAMP, LH	\$	88.41 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	1,099.46 X
1	LINER, REAR WHEEL HOUSE, LH	\$	176.09 X
TOTAL		\$	6,872.82
25%		\$	1,718.20
		\$	5,154.61

Special Nett

1SET DOOR TRIM CLIP	\$	70.00 X
1SET DOOR WEATHERSTRIP CLIP	\$	65.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2407-078**SHD9926D**

- 1 RR BUMPER CLIP
- 1 DOOR STICKER TEL NO.
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	nn	60.00	X
\$	nn	100.00	60mm
\$	nn	65.00	X
\$	nn	65.00	X
TOTAL		\$ 425.00	
TOTAL PARTS		\$ 2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	200l
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	440l
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	5	170.00	X
To Check Electrical Lighting Concerned.	\$	5	170.00	X
To check steering geometry and computer wheel alignment	\$	5	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	5	170.00	X
TOTAL		\$	4,720.00	
Over All Total		\$	12,174.61	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days