

Not Notched
Respray B4 paint

3951.03

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9895J

AAD2407-101

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 AUG 2024

SHD9895J

JTDKB3FU403092551

200303878K

TOYOTA

PRIUS GEN 4

26/7/2024

GBJ2570G/CHINA

11/11/2021

PART

LIST

- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 MOULDING, FRONT BUMPER SIDE, LH

\$	Wt	3,325.56	✓
\$	R	1,236.69	X
\$	Sn	265.55	X
\$	nu	68.88	✓
\$	Bu	659.40	✓
\$	Sn	100.91	X
\$	R	902.16	X
\$	Sn	38.22	X
\$	Sn	100.49	X
\$	Sn	59.85	X
\$	Sn	74.97	X
\$	Wt	120.86	✓

TOTAL \$ 6,953.54

25% \$ 1,738.39

\$ 5,215.16

Special Nett

- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	nu	65.00	65.00
\$	nu	85.00	X
\$	nu	130.00	X
\$	nu	65.00	X

TOTAL \$ 345.00

TOTAL PARTS \$ 2,300.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9895J**AAD2407-101****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	240.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	<i>300</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>440</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	<i>X</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>4</i>	170.00	<i>X</i>
TOTAL	\$		5,100.00	
Over All Total	\$		12,615.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days*04 Days**2 days*