



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref

:

WH3294

Vehicle No.

:

XE2674G

Make & Model

:

SCANIA P360CB6X4MHZ

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
PARTS (LIST ITEMS)						
1	Tail lamp LH / <i>Buit / melt</i>			190.00		
1	Tail lamp guard LH x R			125.00		
1	Tail lamp bracket LH x R			425.00		
				740.00		
Part Items Total: 15%				111.00		
				851.00		
SPECIAL NETT ITEMS						
1	Hooklift Bumper Support / <i>Buit</i>			6000.00		
1	Hooklift Rear Lower Support Roller x R			4000.00		
1	Hooklift Rear Roller with blushing LH / <i>Buit</i>			1000.00		
2	Hooklift Hydraulic Pipes@2*\$380 ?			760.00		
1	Canvass Sheeting System Bar LH / <i>Buit</i>			2250.00		
3	Canvass Sheeting System Bar Bushing LH@3*\$500 ?			1500.00		
1	Canvass Sheeting System Bar Cylinder Shaft LH ?			800.00		
2	Canvass Sheeting System Bar Hydraulic Motor LH@2*\$1500 / <i>Buit</i>			3000.00		
1	Rear Mudguard LH / <i>Buit</i>			900.00		
3	Rear Mudguard Bracket LH@3*\$150 / <i>Buit</i>			450.00		
1	Rear Mudguard Rubber LH / <i>Buit</i>			100.00		
4	Rear Tyre LH@4*\$600 / <i>Buit (70% of \$600)</i>			2400.00		
4	Rear Tyre Rim LH@4*\$900 / <i>Buit</i>			3600.00		
2	Rear Axle Drum@2*\$950 ?			1900.00		
1	Rear Axle Housing ?			9000.00		
1	Rear Spring Leaf Assy LH / <i>Buit</i>			2465.00		
4	Rear Spring Bush LH@4*\$180 / <i>Buit</i>			720.00		
2	Rear U Bolt LH@2*\$150 / <i>Buit</i>			300.00		
4	Torque Rod Bush@6*\$90 / <i>Buit</i>			540.00		
2	Torque Rod Bolt & Nut (Long)@2*\$60 / <i>rec</i>			120.00		
4	Torque Rod Bolt & Nut (Short)@4*\$30 / <i>rec</i>			120.00		
1	Gear Oil / <i>rec</i>			300.00		
1	Rear Brake Chamber Assy@2*\$1800 / <i>Buit</i>			3600.00		
2	Rear Brake Chamber Connector@2*\$150 / <i>Buit</i>			300.00		
SN Items Total:				46125.00		
Total Parts:				46976.00		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH3294
Vehicle No.	: XE2674G
Make & Model	: SCANIA P360CB6X4MHZ

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	Labour to dismantle & renew canvass sheeting system bar , arm,bushing , cylinder shaft ,motor	2000.00	800
2	To remove and refix wiring system at accident damaged area and check for all electrical proper function	300.00	50
3	Labour to dismantle rear hooklift bumper support & dismantle hooklift	2000.00	1000
4	Labour to renew rear hooklift roller & lower support roller .	2000.00	200
5	Labour to renew rear cabin mounting bar & propellar shaft .	1000.00	500
6	Labour to dismantle & refit rear tyres	200.00	150
7	Labour to dismantle & refit spring assy ,torque rod ,torque rod bush,torque rod bolt & nut	800.00	400
8	Labour to renew brake shoe , expander , chamber & housing bracket	600.00	?
9	Labour to dismantle & renew rear axle shaft .	600.00	?
10	To spray & painting on affected area . and 10pc's	3000.00	2000
Labour Total :		12500.00	
TOTAL (PARTS & LABOUR):		59476.00	

Sten CLKK)

28/8/24, 12.00pm

OD - AlM Anthae

Excess - ?

L/S

by AR M
14 dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: ..

Date: