



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH3294				Page No. 1	
Vehicle No. : XE2674G					
Make & Model : SCANIA P360CB6X4MHZ					
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)					
1	Tail lamp LH / <i>Burnt / melt</i>			190.00 /	
1	Tail lamp guard LH x <i>R</i>			125.00	
1	Tail lamp bracket LH x <i>R</i>			425.00	
				740.00	
Part Items Total: 15%				111.00	
				851.00	
SPECIAL NETT ITEMS					
1	Hooklift Bumper Support / <i>Burnt</i>			6000.00	3000 /
1	Hooklift Rear Lower Support Roller x <i>R</i>			4000.00	
1	Hooklift Rear Roller with blushing LH / <i>Burnt</i>			1000.00	400 /
2	Hooklift Hydraulic Pipes@2*\$380 ? / <i>Burnt</i>			760.00	600 /
1	Canvass Sheeting System Bar LH / <i>Burnt</i>			2250.00	/
3	Canvass Sheeting System Bar Bushing LH@3*\$500 ? / <i>Burnt</i>			1500.00	900 /
1	Canvass Sheeting System Bar Cylinder Shaft LH ? / <i>Burnt</i>			800.00	/
2	Canvass Sheeting System Bar Hydraulic Motor LH@2*\$1500 / <i>Burnt</i>			3000.00	2000 /
1	Rear Mudguard LH / <i>Burnt</i>			900.00	/
3	Rear Mudguard Bracket LH@3*\$150 / <i>Burnt</i>			450.00	/
1	Rear Mudguard Rubber LH / <i>Burnt</i>			100.00	/
4	Rear Tyre LH@4*\$600 / <i>Burnt</i> (70% of \$600) = \$420			2400.00	1680 /
4	Rear Tyre Rim LH@4*\$900 / <i>Burnt</i> \$700 x 4			3600.00	2800 /
2	Rear Axle Drum@2*\$950 ? / <i>Burnt</i>			1900.00	1600 /
1	Rear Axle Housing ? x <i>nn</i>			9000.00	
1	Rear Spring Leaf Assy LH / <i>Burnt</i>			2465.00	/
4	Rear Spring Bush LH@4*\$180 / <i>Burnt</i> 150 x 4			720.00	600 /
2	Rear U Bolt LH@2*\$150 / <i>Burnt</i>			300.00	/
4	Torque Rod Bush@6*\$90 / <i>Burnt</i>			540.00	360 /
2	Torque Rod Bolt & Nut (Long)@2*\$60 / <i>rec</i>			120.00	/
4	Torque Rod Bolt & Nut (Short)@4*\$30 / <i>rec</i>			120.00	/
1	Gear Oil / <i>rec</i>			300.00	200 /
1	Rear Brake Chamber Assy@2*\$1800 / <i>Burnt</i>			3600.00	1600 /
2	Rear Brake Chamber Connector@2*\$150 / <i>Burnt</i>			300.00	/
SN Items Total:				46125.00	
Total Parts:				46976.00	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH3294
Vehicle No.	: XE2674G
Make & Model	: SCANIA P360CB6X4MHZ

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	Labour to dismantle & renew canvass sheeting system bar , arm,bushing , cylinder shaft ,motor	2000.00	800
2	To remove and refix wiring system at accident damaged area and check for all electrical proper function	300.00	50
3	Labour to dismantle rear hooklift bumper support & dismantle hooklift	2000.00	1000
4	Labour to renew rear hooklift roller & lower support roller .	2000.00	200
5	Labour to renew rear cabin mounting bar & propellar shaft .	1000.00	500
6	Labour to dismantle & refit rear tyres	200.00	150
7	Labour to dismantle & refit spring assy ,torque rod ,torque rod bush,torque rod bolt & nut	800.00	400
8	Labour to renew brake shoe , expander , chamber & housing bracket	600.00	? x
9	Labour to dismantle & renew rear axle shaft .	600.00	? x
10	To spray & painting on affected area . and 10pc's	3000.00	2000
Labour Total :		12500.00	
TOTAL (PARTS & LABOUR):		59476.00	

5100

Stew CLKK)

28/8/24, 12.00pm

OD - AlM Anthae

Excess - ?

L/S

by AR my
14 by S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: ..

Date:

28,686.50

+

1466.00 (Supp)

= 30,152.50

L/S - 24,122.00

= 24,100.00