

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

24/08/2024

Owner: PRAMKUMAR

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SNR5461J

1pc	rear tailgate	<i>Full way</i>	\$ 1,350.25	✓
1pc	rear tailgate windscreen glass moulding	<i>re</i>	\$ 281.50	✓
1pc	rear tailgate "TOYOTA" logo	<i>re</i>	\$ 85.20	X
1pc	rear tailgate "NOAH" emblem	<i>re</i>	\$ 75.20	X
1pc	rear tailgate "HYBRID" emblem	<i>re</i>	\$ 78.50	✓
1pc	rear tailgate outer garnish	<i>re</i>	\$ 481.50	X
1pc	rear tailgate inner lock	<i>\$ re</i>	\$ 481.20	X
1pc	rear tailgate inner garnish	<i>\$ re</i>	\$ 525.20	X
1pc	rear tailgate inner rubber	<i>\$ re</i>	\$ 181.50	X
1pc	rear bumper	<i>Br</i>	\$ 1,250.20	✓
2pcs	rear bumper reflector @\$121.50	<i>\$ re</i>	\$ 243.00	X
2pcs	rear bumper centre parking sensor @\$380.50	<i>\$</i>	\$ 761.00	7
1pc	rear end panel	<i>\$ re</i>	\$ 781.20	X
1pc	rear end panel inner garnish	<i>\$ re</i>	\$ 381.50	X
			\$ 6,956.95	
			\$ 1,739.24	
			\$ 5,217.71	

less 25%

1 set rear number plate & casing s.nett \$ re 50.00 X

remove & refix rear winscreen glass	\$ 120.00	✓
sealant	<i>\$ re</i> 80.00	<i>40.00</i>
wirring	\$ 80.00	<i>15L</i>
tuffkote	\$ 80.00	<i>30L</i>
spray painting	<i>220L</i> \$ 1,000.00	<i>400L</i>
labour charges	\$ 1,000.00	<i>400L</i>
Total		
	\$ 7,627.71	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: