

Shiau Chan (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 16 January 2025 12:02 PM
To: Hua Chin Motors
Cc: Shiau Chan (LKKAUTO)
Subject: Re: FBE 5816E doa: 17/08/24

Hi ,

As per our message,

We will be advising our principal a cost of repair L/S \$2,450.00 /- with 04 days of repair before GST, subject to their approval.

Best Regards,
Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Wednesday, 4 September 2024 1:58 pm
To: Hua Chin Motors <huachinmotors2@gmail.com>
Subject: Fw: FBE 5816E doa: 17/08/24

Hi,

refer to attachment for the revised estimate

Best Regards,
Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: M Rasul M Yunus <mrasmlyunus@gmail.com>
Sent: Wednesday, 4 September 2024 1:56 pm
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject:

HUA CH

BIKE NO: FBE5

| S/N | DES |
|-----|-----|
| 1 | RIM |