

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23,

#02-02, Midview Building, Singapore 659578

Tel: 68986619 Fax: 62678616

Email: huachinmotors2@gmail.com

BIKE NO: FBE5816E YAMAHA YZF-R15

S/N	DESCRIPTION/ MATERIAL	Quotation
1	RIM repair	\$ 345.00 X
2	HEADLIGHT bu	305 \$ 450.00
3	HEADLIGHT BRACKET bt	\$ 95.00
4	TOP FEARING cm	185 \$ 250.00
5	LEVER scr	\$ 30.00
6	FRONT MUDGUARD cm	65 \$ 75.00
7	HANDLE BAR 26t	126 \$ 180.00
8	DISC scr	25 \$ 125.00
9	FORK bt	\$ 350.00
10	SPEEDOMETER cm	\$ 350.00
11	UNDER BRACKET bt	245 \$ 280.00
12	SIGNAL LIGHT scr	\$ 30.00
13	THROTTLE CABLE ? X SVL	\$ 80.00 X
14	CLUTCH CABLE ? scr	\$ 30.00
15	AIR INTAKE L&R ? X SVL	\$ 90.00 X
16	SIDE COWLING L&R cm scr	230 \$ 360.00 X
17	FOOTREST X SVL	\$ 90.00 X
18	STERING CONE ru	55 \$ 120.00
19	RIM SHAFT ? X SVL	\$ 45.00 X
20	WIND SCREEN cm	45 \$ 150.00 X
21	MIRROR scr	12 \$ 80.00 X
22	EXHAUST PIPE MUFFLER X SVL	\$ 650.00 X
TOTAL		\$ 4,255.00
(LESS 10% DISCOUNT)		\$ 425.50
PLUS 7% GST		\$ 3,829.50
		\$ 344.66
		\$ 4,174.16
Add special nett items from above		
23	TOWING FEE receipt	\$? 60.00
24	NO. PLATE ms	520 \$ 10 35.00
25	ALIGN BODY	\$ 150 200.00
26	LABOUR CHARGES	\$ 300 400.00
Lump sum repair adjustment		\$ 4,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 907010068
4 days

4/5
28/08/24

Resurvey after repair

painting \$400

signal switch 75 ~~495~~ cut 75-10% = 67.50

AFTER PAINTING \$500

2068.20

520.00

67.50

400.00

3055.70

20%

2444.56

415-2450/

4 days