



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2500551

INV Date 21/01/2025

Reference CD/LPC24080475/Eua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 4168T
Insured Veh. GBE 6182T
Claim No. 24/24/24/VC05/029765
Policy No. Z24VC05025878
Accident Date 27/08/2024
Inspection Date 28/08/2024

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (9%)	22.50
Grand Total	272.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24080475/Eua3q2
300 BEACH ROAD	Date:	21/01/2025
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	GBE 6182T	Veh. Inspected	SHB 4168T
Policy No.	Z24VC05025878	Coverage	0
Claim No.	24/24/24/VC05/029765	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	27/08/2024

2. Vehicle Details

Make & Model	HYUNDAI SX2 KONA 1.6 GDI HEV	C.C	1580
Engine No.	G4LLRU441061	Year of Reg.	31/07/2024
Chassis No.	KMHXB811VSU079680	Colour	BLUE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	206/65 R16	KUMHO	7
L/H Front Tyre	206/65 R16	KUMHO	7
R/H Rear Tyre	206/65 R16	KUMHO	7
L/H Rear Tyre	206/65 R16	KUMHO	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/08/2024	Inspection Date	28/08/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHB 4168T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR PANEL RH	DENTED	\$1,789.00	\$1,789.00
1	FRONT DOOR GARNISH RH	CUT	\$400.00	\$400.00
1	FRONT DOOR HINGE RH	NOT NECESSARY	\$46.00	\$0.00
1	FRONT FENDER GARNISH RH	CUT	\$663.00	\$663.00
1	MOULDING ASSY -SIDE SILL RH	NOT NECESSARY	\$340.00	\$0.00
1	FRONT FENDER PANEL RH	TO REPAIR SEE LABOUR	\$928.00	\$0.00
	LESS 20.00% DISCOUNT		(\$833.20)	(\$570.40)
			\$3,332.80	\$2,281.60
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR COMFORT LOGO STICKER (SN)	NECESSARY	\$75.00	\$75.00
			\$75.00	\$75.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER PANEL RH.		\$950.00	\$380.00
	SPRAY PAINTING CHARGE		\$700.00	\$560.00
	REMOVE/REFIX DOOR PARTS		\$90.00	\$50.00
			\$1,740.00	\$990.00
GRAND TOTAL			\$5,147.80	\$3,346.60
RECOMMENDED COST OF REPAIRS				\$3,346.60
Report Ref No: CD/LPC24080475/Eua3q2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T



PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 9)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 4168T

