

3AMB / 33FMD
106, Upper Jurong Rd
Blk 109 #01-12
Singapore 638360

Ref: 3AMB/33MOS/013/24
Date: 15/10/2024

Tel: 6410 4269

FINAL COST OF REPAIR

Vehicle No.	MID34825	Type of Repair	SRO-ACCIDENT
Vehicle Type	AGILIS LUV	SR / SWD	-
Unit	1 SAF TPT BN	MO No.	8203085340

S/N	Damaged Description	Remarks
1	LHR BODY DENTED	-N.A.-
2	REAR CABIN DOOR HARD TO CLOSE	-N.A.-
2	FRONT BONNET RED CROSS SIGN RUSTY	-N.A.-
	---LAST ENTRY---	

S/N	Type of Repair Cost	Amount
1	SUB-CON	\$1,440.00
2	MARK UP 20%	\$1,728.00
3	ADD JOB (ENDORSED BY SYSTEM MANAGER)	\$1,190.00
4	MARK UP 20%	\$1,428.00
5	GENERAL SERVICE (TOWING)	\$600.88
TOTAL REPAIR COST		\$3,756.88

Remarks:

**Above costings only for Depot Level repair by STELS's.*
Ref No.: SAF 1222 Report No.: BB72/JRN/D/009/24

Prepared by:

MOHAMED SUHAIMI
BIN ZAKARIA

Digitally signed by MOHAMED
SUHAIMI BIN ZAKARIA
Date: 2024.10.15 12:44:45
+08'00'

ME3 MD SUHAIMI
HD MOS 3AMB/33FMD

OVERVIEW OF JOBSCOPE

S/ No	DESCRIPTION	LABOUR(HRS)	LABOUR RATE(SGD)	TOTAL (SGD)
	34825MID(NSN:320856216)			
1	To carry out repair & respray rear cabin barn door, rear cabin towing hinge LH, rear number plate base.	12.0	\$100.00	\$1200.00
2	Site Survey (Engineer)	2.0	\$120.00	\$240.00
			TOTAL COST	\$1440.00

S/ No	SPARES DESCRIPTION	QTY	UNIT PRICE (SGD)	TOTAL (SGD)
	NIL	-	-	-
			TOTAL COST	\$0.00
	---Last Entry---			

Total Labour Cost: \$1440.00
Total Spare Cost: NIL
Grand Total: \$1,440.00

OVERVIEW OF ADD-JOB

S/ No	DESCRIPTION	LABOUR(HRS)	LABOUR RATE(SGD)	TOTAL (SGD)
	34825MID(NSN:320856216)			
1	To carry out repair and respray front bonnet	10.0	\$100.00	\$1000.00
			TOTAL COST	\$1000.00

S/ No	SPARES DESCRIPTION	QTY	UNIT PRICE (SGD)	TOTAL (SGD)
1	Decal: Red Cross, Hood (500x500mm)	1	\$190.00	\$190.00
			TOTAL COST	\$190.00

Total Labour Cost: \$1000.00
Total Spare Cost: \$190.00
Grand Total: \$1,190.00