



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|-------------------------------------|-------|---------------------|
| MS LIBERTY INSURANCE PTE LTD | Ref: | CS/LIP24080477/Uqh3 |
| ONE RAFFLES QUAY #25-01 NORTH TOWER | Date: | 23/09/2024 |
| SINGAPORE 048583 | Code: | LIP |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SLG 7518Z | Veh. Inspected | SMR 8227L |
| Policy No. | - | Coverage | 0 |
| Claim No. | AVS24/2657 | Excess | \$0.00 |
| Assign From | ANDY SEAH | Assign Date | 27/08/2024 |

2. Vehicle Details

| | | | |
|-----------------|---------------------|--------------|------------|
| Make & Model | HONDA FIT 1.3GF (A) | C.C | 1317 |
| Engine No. | L13B3932845 | Year of Reg. | 23/01/2020 |
| Chassis No. | GK33418355 | Colour | GREY |
| Odometer | 56155 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|-------------|--------------|
| R/H Front Tyre | 175/70R14 | BRIDGESTONE | 6 |
| L/H Front Tyre | 175/70R14 | BRIDGESTONE | 6 |
| R/H Rear Tyre | 175/70R14 | BRIDGESTONE | 6 |
| L/H Rear Tyre | 175/70R14 | BRIDGESTONE | 6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 26/08/2024 | Inspection Date | 28/08/2024 |
| Survey held at | FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days