



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBW939Y
MAKE/MODEL : YAM / XMAX300

NO. : 47477

DATE : 16/05/2024

CLAIM NO. : 12582

POLICY NO. :

FROM : RAYMOND

N of Accident
90096608 Linc
no-213
28/8/24
P/P 99615-70
5 days
Chenghe ARB up

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	ARM REAR ASSY P/N: 66506 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	279.00 X
2	AXLE WHEEL FRONT P/N: 56617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
3	BALANCER HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
4	BAND MUFFLER P/N: 67385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
5	BEARING STEERING CONE LOWER P/N: 27589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00
6	BEARING STEERING CONE UPPER P/N: 27588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00
7	BEARING WHEEL FRONT P/N: 56596 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$22.00	44.00
8	BELLY PAN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
9	BODY FRONT UNDER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00

*47477

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- *to display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



DATA PROTECTION
ASSURED

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	BOLT FLANGE - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	<i>nee</i> 6.00
11	BOX 3 RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	<i>cu7</i> 12.00
12	BOX REAR ALUMINUM 55L (SILVER-X) P/N: 82078 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$260.00	<i>cm</i> 260.00
13	BRACKET (TAIYA) BOX REAR P/N: 82076 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$307.00	<i>cu7</i> 307.00
14	BRACKET ENGINE COMP P/N: 66513 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$294.00	<i>Buf/Tm</i> 294.00
15	BRACKET UNDER FORK P/N: 67552 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$465.00	<i>Buf</i> 465.00
16	BRAKE LEVER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	<i>sum</i> 28.00
17	BUZZER P/N: 68364 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	<i>nee</i> 42.00
18	CALIPER FRONT RH P/N: 56616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$214.00	<i>Tm</i> 214.00
19	CAP PROTECTOR EXHAUST P/N: 62329 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	<i>gmsl</i> 42.00
20	CLIP COVER (PLASTIC) P/N: 56586 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$6.00	<i>nee</i> 60.00
21	COOLANT (BMW) P/N: 56295 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	<i>nee</i> 46.00
22	COVER CAP PROTECTOR EXHAUST INNER P/N: 67573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	<i>cu7</i> 40.00
23	COVER COMPARTMENT BOX RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	<i>cu7</i> 19.00
24	COVER EXHAUST INNER P/N: 82824 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	<i>cu7</i> 45.00

2227

*47477 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	COVER EXHAUST PAD P/N: 82823 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	Cu 20.00
26	COVER FLASHER SPEEDOMETER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	Baye 28.00
27	COVER FRONT UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	Cu 28.00
28	COVER FRONT UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	Cu 70.00
29	COVER LOWER SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	Cu 43.00
30	COVER PANEL SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	Cu 46.00
31	COVER REAR SIDE COWLING RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	Cu 43.00
32	COVER TAIL REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	Cu 23.00
33	COWLING FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	FW 43.00
34	COWLING FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	Cu 43.00
35	CROWN HANDLE P/N: 56569 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$214.00	FW 214.00
36	DAMPER PLATE - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	FW 6.00
37	DUCT 1 P/N: 56591 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	FW 25.00
38	EMBLEM P/N: 72386 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	FW 14.00
39	EMBLEM 3D - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	FW 28.00

*47477 *

DATA PROTECTION
ASSUREDbizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	EMBLEM BLUE CORE P/N: 56570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	<i>nm</i> 9.00
41	EMBLEM YAMAHA - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.00	<i>nm</i> 8.00
42	FENDER FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	<i>cm</i> 34.00
43	FOOTBOARD RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	<i>cm</i> 51.00
44	FORK FORNT ASSY LH P/N: 79879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	<i>341</i> 341.00
45	FORK FORNT ASSY RH P/N: 79880 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	<i>D.S</i> 341.00
46	GASKET EXHAUST PIPE P/N: 62317 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	<i>nm</i> 9.00
47	GASKET MUFFLER P/N: 62310 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	<i>nm</i> 9.00
48	GRILL AIR INTAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	<i>cm</i> 34.00
49	GROMMET EXHAUST P/N: 75722 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	<i>nm</i> 16.00
50	HANDLE BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	<i>Bat</i> 50.00
51	HEADLAMP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$744.00	<i>cm</i> 744.00
52	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	☒ Supply/Install	28.00	\$85.00	<i>600</i> 2,380.00
53	LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$101.00	<i>cm</i> 101.00
54	LEG SHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	<i>cm</i> 56.00

4704

*47477 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
55	MAT 4 P/N: 67368 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	CU7 17.00
56	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,628.00	ONE 1,628.00
57	MIRROR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	CU7 70.00
58	MUFFLER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,240.00 1040	DD 1,240.00 1040
59	OIL FORK (ELF PERFO) XC 10W P/N: 62236 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	MAN 12.00
60	PANEL CONSOLE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	CU7 17.00
61	PIPE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	MAN 40.00 X
62	PIPE EXHAUST FRONT P/N: 67369 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	Range 70.00
63	PLATE DISC BRAKE FRONT P/N: 56624 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$116.00	Bul 116.00
64	PROTECTOR EXHAUST P/N: 62321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	CU7 94.00
65	RADIATOR ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	DD 388.00
66	REAR FOOTREST ASSY 2 P/N: 67360 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	CU7 59.00
67	REPAIR ON ALIGNMENT BODY - (REPORTED BY MECHANIC)	Repair	1.00	\$1,240.00	\$ 500 1,240.00
68	RIM SPORT FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$496.00	Bent/wrong 496.00
69	ROTOR SENSOR P/N: 60803 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	Range 31.00

8747

*47477 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
70	SEAL STEERING CONE P/N: 27596 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
71	SEAL WHEEL FRONT P/N: 67590 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
72	SENSOR LEAN ANGLE P/N: 70231 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
73	SHAFT PIVOT P/N: 66494 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
74	SHIELD HEAT MUFFLER SIDE 2 P/N: 67593 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
75	SHOCK ABSORBER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$124.00	248.00
76	STAND MAIN P/N: 56589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$149.00	149.00
77	STAY 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00
78	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	29.00
79	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - BIKE TOWED BACK TO BHH		1.00	\$70.00	70.00
80	TYRE 120/70-15 (MICHELLIN) CITY GRIP II P/N: 62301 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$150.00	150.00
81	UPPER COVER METER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
82	VALVE RIM P/N: 57073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
83	WINDSHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00

SUB TOTAL

\$14,077.00


GST @ 9 %

\$1,266.93

GRAND TOTAL (SGD)

\$15,343.93

*47477 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	50% deposit required before ordering of parts.				

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*47477 *



bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

NO. : 48293

Supplementary 1 To QTN: 47477

DATE : 18/11/2024

CLAIM NO. : 12582

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBW939Y
MAKE/MODEL : YAM / XMAX300


S/N	Description	Action	Qty	Unit Price	Amount
1	BODY FRONT UNDER LH P/N: 85245	Replace	1.00	\$42.00	42.00
2	COVER MUDGUARD RH P/N: 86191	Replace	1.00	\$27.00	27.00
SUB TOTAL					\$69.00
GST @ 9 %					\$6.21
GRAND TOTAL (SGD)					\$75.21

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*48293 *



bizSAFE₃

