



BAN HOCK HIN
Co., Pte Ltd

Rev 11

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

21 NOV 2024

Your Ref : D24004296MFCT
Our Ref : TP/12582/FBW939Y/SHA4573L

MS First Capital Insurance Ltd
16 Raffles Quay
#42-01 Hong Leong Building
Singapore 048581

ATTN: Ms Emily Tan

Dear Emily,

Accident Involving FBW939Y & SHA4573L on 11/05/2024

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 9% GST)	\$10,481.11
2. Loss of Use (5 days x \$30)	\$ 100.00
3. GIA Vehicle Insurance Search Fee	\$ 2.18
TOTAL	<u>\$10,583.29</u>

We attached our Tax Invoice, GIA Search Invoice, Letter of Authorisation and Traffic Police Investigation Result for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

.....
Raymond Tan
Insurance Dept



LETTER OF AUTHORISATION

Your Ref : D24004296MFCT / CTPL / TPD 2
Our Ref : TP/12582/FBW939Y/SHA4573L

BY FAX & HAND

MS First Capital Insurance Ltd
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN : Motor Claims Dept

Dear Sir / Madam,

Accident Involving FBW939Y & SHA4573L on 11/05/2024

AUTHORIZATION LETTER

I / We refer to the above-mentioned matter.

I / We, **Central Narcotics Bureau** hereby irrevocably authorize Ban Hock Hin Co., Pte Ltd to act on our behalf to file a 3rd Party Claim against your insured **SHA4573L**.

I / We further authorize M/s **MS First Capital Insurance Ltd** to release the claim and payment to M/s Ban Hock Hin Co., Pte Ltd in consideration of their allowing me to take possession of my motorcycle **FBW939Y** upon completion of repairs.

If you need any verification from us, kindly direct all enquiries and correspondences to M/s Ban Hock Hin Co., Pte Ltd.

Yours faithfully

Witness



MUHAMMAD FAIZAL BAHARIN
HEAD INTELLIGENCE III
INTELLIGENCE DIVISION

.....
Claimant (Signature & Company Stamp)
CENTRAL NARCOTICS BUREAU
SINGAPORE

Central Narcotics Bureau

.....
Name & NRIC No

.....
Witness Signature


.....
Tan Chou Lok / 9111523R
.....
Name & NRIC No

DISCHARGE RECEIPT

CLAIM REFERENCE : D24004296MFCT/CTPL/TPD 2
ACCIDENT DATE : 11/05/2024
ACCIDENT LOCATION : UPPER THOMSON RD SHELL PETROL STATION
INSURED : COMFORT TRANSPORTATION PTE LTD
INSURED DRIVER : HENG HUA SUNG
INSURED VEHICLE : SHA4573L
INVOLVED PARTY : FBW939Y
SETTLEMENT SUM : \$10,580.00

I/We, the undernoted CLAIMANT being the person/entity entitled to receive the compensation in relation to the accident, hereby agree to accept the SETTLEMENT SUM as full and final settlement of all claims for damages, costs & disbursements arising out of the ACCIDENT, and I/WE also agree that the said settlement sum:

1. is paid without admission of liability on the part of MS First Capital Insurance Limited and/or its INSURED and/or its INSURED DRIVER in respect of the said loss and for damage whether now or hereafter to become manifest,
2. is accepted by me/us to the intent that the said MS First Capital Insurance Limited and /or its INSURED and/or its INSURED DRIVER be absolutely and finally discharged from all claims whatsoever which I/WE now or hereafter may have arising out of or connected with or traceable to the said accident.

I/WE acknowledge that this DISCHARGE RECEIPT is not to be construed as an admission of liability on the part of MS First Capital Insurance Limited and/or its INSURED and /or its INSURED DRIVER and it shall not be used as evidence in any claims or actions which may be made against them or any of them.

CLAIMANT: Muhammad Faizal Baharin



Signature and Date :

AS Faizal

12 Jan 2025

WITNESS : *Tan Chok Lok*

Signature and Date :

Wale 12/01/2025



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

MOTOR CLAIMS DEPT

Invoice No. : **DLCR40122572-I12582**
Invoice Date : 18/11/2024
Payment Due Date : 18/12/2024

CLAIM NO. : 12582
POLICY NO. :
VEHICLE NO. : FBW0939Y
MAKE/MODEL : YAM / XMAX300

S/N	Description	Action	Qty	Unit Price	Amount
1	REPAIR ON ALIGNMENT BODY	Repair	1	\$500.00	\$500.00
2	BALANCER HANDLE	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
3	BAND MUFFLER	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
4	BEARING STEERING CONE LOWER	REPLACE	1	\$74.00	\$66.60
				Disc %: 10%	
5	BEARING STEERING CONE UPPER	REPLACE	1	\$74.00	\$66.60
				Disc %: 10%	
6	BEARING WHEEL FRONT	REPLACE	2	\$22.00	\$39.60
				Disc %: 10%	
7	BELLY PAN	REPLACE	1	\$50.00	\$45.00
				Disc %: 10%	
8	BODY FRONT UNDER RH	REPLACE	1	\$43.00	\$38.70
				Disc %: 10%	
9	BOLT FLANGE	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
10	BOX 3 RH	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
11	BOX REAR ALUMINUM 55L (SILVER-X)	REPLACE	1	\$260.00	\$234.00
				Disc %: 10%	
12	BRACKET (TAIYA) BOX REAR	REPLACE	1	\$307.00	\$276.30
				Disc %: 10%	
13	BRACKET ENGINE COMP	REPLACE	1	\$294.00	\$264.60
				Disc %: 10%	
14	BRACKET UNDER FORK	REPLACE	1	\$465.00	\$418.50
				Disc %: 10%	
15	BRAKE LEVER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
16	BUZZER	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
17	CALIPER FRONT RH	REPLACE	1	\$214.00	\$192.60
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
18	CAP PROTECTOR EXHAUST	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
19	CLIP COVER (PLASTIC)	REPLACE	10	\$6.00	\$54.00
				Disc %: 10%	
20	COOLANT (BMW)	REPLACE	1	\$46.00	\$41.40
				Disc %: 10%	
21	COVER CAP PROTECTOR EXHAUST INNER	REPLACE	1	\$40.00	\$36.00
				Disc %: 10%	
22	COVER COMPARTMENT BOX RH	REPLACE	1	\$19.00	\$17.10
				Disc %: 10%	
23	COVER EXHAUST INNER	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
24	COVER EXHAUST PAD	REPLACE	1	\$20.00	\$18.00
				Disc %: 10%	
25	COVER FLASHER SPEEDOMETER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
26	COVER FRONT UNDER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
27	COVER FRONT UPPER	REPLACE	1	\$70.00	\$63.00
				Disc %: 10%	
28	COVER LOWER SIDE RH	REPLACE	1	\$43.00	\$38.70
				Disc %: 10%	
29	COVER PANEL SIDE RH	REPLACE	1	\$46.00	\$41.40
				Disc %: 10%	
30	COVER REAR SIDE COWLING RH	REPLACE	1	\$43.00	\$38.70
				Disc %: 10%	
31	COVER TAIL REAR RH	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
32	COWLING FRONT LH	REPLACE	1	\$43.00	\$38.70
				Disc %: 10%	
33	COWLING FRONT RH	REPLACE	1	\$43.00	\$38.70
				Disc %: 10%	
34	CROWN HANDLE	REPLACE	1	\$214.00	\$192.60
				Disc %: 10%	
35	DAMPER PLATE	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
36	DUCT 1	REPLACE	1	\$25.00	\$22.50
				Disc %: 10%	
37	EMBLEM	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
38	EMBLEM 3D	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
39	EMBLEM BLUE CORE	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
40	EMBLEM YAMAHA	REPLACE	2	\$4.00	\$7.20
				Disc %: 10%	
41	FENDER FRONT	REPLACE	1	\$34.00	\$30.60
				Disc %: 10%	
42	FOOTBOARD RH	REPLACE	1	\$51.00	\$45.90
				Disc %: 10%	
43	FORK FORNT ASSY LH	REPLACE	1	\$341.00	\$306.90
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
44	FORK FORNT ASSY RH	REPLACE	1	\$341.00	\$306.90
				Disc %: 10%	
45	GASKET EXHAUST PIPE	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
46	GASKET MUFFLER	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
47	GRILL AIR INTAKE	REPLACE	1	\$34.00	\$30.60
				Disc %: 10%	
48	GROMMET EXHAUST	REPLACE	2	\$8.00	\$14.40
				Disc %: 10%	
49	HANDLE BAR	REPLACE	1	\$50.00	\$45.00
				Disc %: 10%	
50	HEADLAMP ASSY	REPLACE	1	\$744.00	\$669.60
				Disc %: 10%	
51	LABOUR	Supply/Install	1	\$600.00	\$600.00
52	LAMP SIGNAL FRONT RH	REPLACE	1	\$101.00	\$90.90
				Disc %: 10%	
53	LEG SHIELD	REPLACE	1	\$56.00	\$50.40
				Disc %: 10%	
54	MAT 4	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
55	METER ASSY	REPLACE	1	\$1,628.00	\$1,465.20
				Disc %: 10%	
56	MIRROR RH	REPLACE	1	\$70.00	\$63.00
				Disc %: 10%	
57	MUFFLER ASSY	REPLACE	1	\$1,040.00	\$936.00
				Disc %: 10%	
58	OIL FORK (ELF PERFO) XC 10W	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
59	PANEL CONSOLE 2	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
60	PIPE EXHAUST FRONT	REPLACE	1	\$70.00	\$63.00
				Disc %: 10%	
61	PLATE DISC BRAKE FRONT	REPLACE	1	\$116.00	\$104.40
				Disc %: 10%	
62	PROTECTOR EXHAUST	REPLACE	1	\$94.00	\$84.60
				Disc %: 10%	
63	RADIATOR ASSY	REPLACE	1	\$388.00	\$349.20
				Disc %: 10%	
64	REAR FOOTREST ASSY 2	REPLACE	1	\$59.00	\$53.10
				Disc %: 10%	
65	RIM SPORT FRONT	REPLACE	1	\$496.00	\$446.40
				Disc %: 10%	
66	ROTOR SENSOR	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
67	SEAL STEERING CONE	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
68	SEAL WHEEL FRONT	REPLACE	2	\$5.00	\$9.00
				Disc %: 10%	
69	SENSOR LEAN ANGLE	REPLACE	1	\$51.00	\$45.90
				Disc %: 10%	
70	SHAFT PIVOT	REPLACE	1	\$25.00	\$22.50
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
71	SHIELD HEAT MUFFLER SIDE 2	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
72	SHOCK ABSORBER	REPLACE	2	\$124.00	\$223.20
				Disc %: 10%	
73	STAY 1	REPLACE	1	\$186.00	\$167.40
				Disc %: 10%	
74	UPPER COVER METER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
75	VALVE RIM	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
76	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A	Supply/Install	1	\$35.00	\$35.00
77	AXLE WHEEL FRONT	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
78	BODY FRONT UNDER LH	Replace	1	\$42.00	\$37.80
				Disc %: 10%	
79	COVER MUDGUARD RH	Replace	1	\$27.00	\$24.30
				Disc %: 10%	

SUB TOTAL \$9,615.70

GST @ 9 % \$865.41

GRAND TOTAL (SGD) \$10,481.11

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



UEN: 197000288K

For Bank Transfer:

Name of bank account (Beneficiary): BAN HOCK HIN CO. PTE LTD

Name of Bank: DBS BANK LTD

Bank Account Number: 025 008 566 3 (Current Account)

Bank Code: 7171 Branch Code: 025 Swift Code: DBSSSGSG

Branch: TOWNER ROAD BRANCH

Address: BLK 101 TOWNER ROAD #01-238 SINGAPORE 322101

Printed by : RAYMOND




INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SHA4573L

Date of Accident

11/05/2024 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance MS First Capital Insurance Ltd

Period of Insurance 01/01/2024 - 31/12/2024

Requested By Tan Chok Lok (Ban Hock Hin C...

Requested Date 28/08/2024 10:07

Payment details

Request Amount: **S\$2**GST Amount: **S\$0.18**Total Amount Due (GST Inclusive): **S\$2.18**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Daphne Lee (LKK Auto)

From: raymond <raymond@bhh.com.sg>
Sent: Monday, 13 January 2025 3:38 PM
To: Daphne Lee (LKK Auto)
Cc: Admin A
Subject: RE: DV - (OUR REF: D24004296MFCT/CTPL/TPD 2) Accident Involving FBW939Y & SHA4573L on 11/05/2024 ***LKK Ref: CD/FCI24080480/Uma3
Attachments: First Capital DV - FBW939Y.pdf

Dear Daphne,

We attached the signed DV for your perusal.

Please refer to our bank particulars below.

Company Name	Ban Hock Hin Company Private Limited
Contact Number	6281 6520
GST Registration Date	01/04/94
GST Registration Number	M2-0010542-7
Contact Email (for payment advice to be sent to)	raymond@bhh.com.sg

Beneficiary's Bank's Details

Bank Name	DBS Bank Ltd
Bank Branch	Towner Road
Bank Address	12 Marina Boulevard, DBS Asia Central, Marina Bay Financial Centre Tower 3, Singapore 018982
Bank Code	7171
Branch Code	025
SWIFT Code	DBSSSGSG

Beneficiary's Details

Beneficiary's Name	Ban Hock Hin Company Private Limited
Beneficiary's Account No.	025-0085663
Beneficiary's Registered Address	No 8 Defu South Street 1 #04-28 S(533758)
Beneficiary's Mailing Address	No 8 Defu South Street 1 #04-28 S(533758)

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <https://www.bhh.com.sg>

Facebook: <https://www.facebook.com/bhhsq>

Daphne Lee (LKK Auto)

From: Emily Tan Su Min <EmilyTan@msfirstcapital.com.sg>
Sent: Friday, 3 January 2025 2:15 PM
To: Daphne Lee (LKK Auto)
Cc: Admin A
Subject: RE: (OUR REF: D24004296MFCT/CTPL/TPD 2) Accident Involving FBW939Y & SHA4573L on 11/05/2024 ***LKK REF: CD/FCI24080480/Uma3

Dear Daphne

Please proceed and offer as per below:

COR - \$10,481.11
LOU - \$100.00 to \$150.00 (\$20-\$30X 5D)
GIA fee - \$2.18
Total – **\$10,583.29 TO \$10,633.29**

Thank you

Emily Tan
Motor Claims Dept.

MS First Capital Insurance Ltd
16 Raffles Quay
#42-01 Hong Leong Building
Singapore 048581

Website <http://www.msfirstcapital.com.sg>

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice:

This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Daphne Lee (LKK Auto) <daphnelee@lkkauto.com>
Sent: Thursday, 2 January 2025 11:12 am
To: Emily Tan Su Min <EmilyTan@msfirstcapital.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: (OUR REF: D24004296MFCT/CTPL/TPD 2) Accident Involving FBW939Y & SHA4573L on 11/05/2024
***LKK REF: CD/FCI24080480/Uma3

EXTERNAL EMAIL - This email was sent by a person from outside your organization. Exercise caution when clicking links, opening attachments or taking further action, before validating its authenticity.

Dear Emily,

Your Ref: D24004296MFCT/CTPL/TPD 2

We refer to the above matter and your email below.

ACCIDENT INVOLVING FBW 939Y AND SHA 4573L ON 11/05/2024

We have highlighted to your good office on 28/08/2024 of Third-Party's request to do Direct Settlement with our Principal, MS First Capital Limited.

It is an accident under BOLA:NIL. OID left turning into petrol station collided TP going straight from left lane..

Basing on the report of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **BAN HOCK HIN CO., PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 14,146.00	\$ 10,481.11 (P/P) (w/GST)
2. Loss of Use (5 days x \$30.00)	\$ 150.00	\$ 100.00 (5 days x \$20.00)
3. LTA/GIA Search Fee	\$ 2.18	\$ 2.18
Total	\$ 14,298.18	\$ 10,583.29

*5 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

Kindly note that this inspection report dated 02/01/2025 is only for mandate purpose.

The above is for your approval please.

Thank You

Cheers to a *Wonderful Christmas* and a *Happy New Year 2025* !

Best Regards,

Daphne Lee (Ms) | Case Handler

Third Party Direct Settlement

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 | Email: DaphneLee@lkkauto.com

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Emily Tan Su Min <EmilyTan@msfirstcapital.com.sg>

Sent: Thursday, 26 December 2024 4:25 PM

To: raymond <raymond@bhh.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Daphne Lee (LKK Auto) <daphnelee@lkkauto.com>

Subject: RE: Accident Involving FBW939Y & SHA4573L on 11/05/2024

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Raymond

Thank you for the phone conversation earlier.

We are well-aware of this matter and to inform you, LKK will revert once their paperwork has been completed.

Please note that our finance is also closed for the year and we are unable to make any payments until 2025.