



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 47477

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

DATE : 16/05/2024
CLAIM NO. : 12582
POLICY NO. :

ATTN: MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBW939Y
MAKE/MODEL : YAM / XMAX300

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	ARM REAR ASSY P/N: 66506 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	279.00
2	AXLE WHEEL FRONT P/N: 56617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
3	BALANCER HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
4	BAND MUFFLER P/N: 67385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
5	BEARING STEERING CONE LOWER P/N: 27589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00
6	BEARING STEERING CONE UPPER P/N: 27588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	74.00
7	BEARING WHEEL FRONT P/N: 56596 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$22.00	44.00
8	BELLY PAN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
9	BODY FRONT UNDER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00

*47477 *



bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	BOLT FLANGE - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	6.00
11	BOX 3 RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
12	BOX REAR ALUMINUM 55L (SILVER-X) P/N: 82078 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$260.00	260.00
13	BRACKET (TAIYA) BOX REAR P/N: 82076 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$307.00	307.00
14	BRACKET ENGINE COMP P/N: 66513 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$294.00	294.00
15	BRACKET UNDER FORK P/N: 67552 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$465.00	465.00
16	BRAKE LEVER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
17	BUZZER P/N: 68364 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
18	CALIPER FRONT RH P/N: 56616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$214.00	214.00
19	CAP PROTECTOR EXHAUST P/N: 62329 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
20	CLIP COVER (PLASTIC) P/N: 56586 - (REPORTED BY MECHANIC)	REPLACE	10.00	\$6.00	60.00
21	COOLANT (BMW) P/N: 56295 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	46.00
22	COVER CAP PROTECTOR EXHAUST INNER P/N: 67573 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
23	COVER COMPARTMENT BOX RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
24	COVER EXHAUST INNER P/N: 82824 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00

*47477 *

DATA PROTECTION
ASSUREDbizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	COVER EXHAUST PAD P/N: 82823 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	20.00
26	COVER FLASHER SPEEDOMETER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
27	COVER FRONT UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
28	COVER FRONT UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00
29	COVER LOWER SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00
30	COVER PANEL SIDE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	46.00
31	COVER REAR SIDE COWLING RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00
32	COVER TAIL REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
33	COWLING FRONT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00
34	COWLING FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$43.00	43.00
35	CROWN HANDLE P/N: 56569 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$214.00	214.00
36	DAMPER PLATE - (REPORTED BY MECHANIC)	REPLACE	2.00	\$3.00	6.00
37	DUCT 1 P/N: 56591 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
38	EMBLEM P/N: 72386 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
39	EMBLEM 3D - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00

*47477 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
40	EMBLEM BLUE CORE P/N: 56570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
41	EMBLEM YAMAHA - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.00	8.00
42	FENDER FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
43	FOOTBOARD RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
44	FORK FORNT ASSY LH P/N: 79879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00
45	FORK FORNT ASSY RH P/N: 79880 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00
46	GASKET EXHAUST PIPE P/N: 62317 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
47	GASKET MUFFLER P/N: 62310 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
48	GRILL AIR INTAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
49	GROMMET EXHAUST P/N: 75722 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00
50	HANDLE BAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00
51	HEADLAMP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$744.00	744.00
52	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	28.00	\$85.00	2,380.00
53	LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$101.00	101.00
54	LEG SHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	56.00

*47477 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
55	MAT 4 P/N: 67368 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
56	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,628.00	1,628.00
57	MIRROR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00
58	MUFFLER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,240.00	1,240.00
59	OIL FORK (ELF PERFO) XC 10W P/N: 62236 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
60	PANEL CONSOLE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
61	PIPE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
62	PIPE EXHAUST FRONT P/N: 67369 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00
63	PLATE DISC BRAKE FRONT P/N: 56624 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$116.00	116.00
64	PROTECTOR EXHAUST P/N: 62321 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	94.00
65	RADIATOR ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00
66	REAR FOOTREST ASSY 2 P/N: 67360 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	59.00
67	REPAIR ON ALIGNMENT BODY - (REPORTED BY MECHANIC)	Repair	1.00	\$1,240.00	1,240.00
68	RIM SPORT FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$496.00	496.00
69	ROTOR SENSOR P/N: 60803 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00

*47477 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
70	SEAL STEERING CONE P/N: 27596 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
71	SEAL WHEEL FRONT P/N: 67590 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
72	SENSOR LEAN ANGLE P/N: 70231 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
73	SHAFT PIVOT P/N: 66494 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$25.00	25.00
74	SHIELD HEAT MUFFLER SIDE 2 P/N: 67593 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
75	SHOCK ABSORBER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$124.00	248.00
76	STAND MAIN P/N: 56589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$149.00	149.00
77	STAY 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00
78	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	29.00
79	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - BIKE TOWED BACK TO BHH		1.00	\$70.00	70.00
80	TYRE 120/70-15 (MICHELLIN) CITY GRIP II P/N: 62301 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$150.00	150.00
81	UPPER COVER METER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
82	VALVE RIM P/N: 57073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
83	WINDSHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00

SUB TOTAL

\$14,077.00

GST @ 9 %

\$1,266.93

GRAND TOTAL (SGD)

\$15,343.93

*47477 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

	50% deposit required before ordering of parts.				
--	--	--	--	--	--

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*47477 *

bizSAFE₃



**SINGAPORE
POLICE FORCE**
SAFEGUARDING EVERY DAY

Our Ref: TP/IP/14130/2024
Date: 22/07/2024

000033

LIM CHEE HENG JIMMY
655 SENJA ROAD
#14-272
SINGAPORE 670655

Traffic Police
10 Ubi Avenue 3
Singapore 408865

<https://eservices.police.gov.sg>

Dear Sir

**TRAFFIC ACCIDENT INVOLVING FBW939Y AND SHA4573L ALONG UPPER THOMSON ROAD
ON 11/05/2024 @ 7.26 PM**

I refer to the above accident.

2 We have completed our investigation into the case. Action has been initiated against the driver of SHA4573L for the offence of careless driving without reasonable consideration causing hurt under sec 65(1)(b) punishable under 65(4)(a) of the road traffic act, 1961.

3 Please be informed that our decision does not preclude you from pursuing insurance / civil claims.

4 If you have any clarification, you may contact the Investigation Officer, Sharon Ye Jiahui at office number: 96793952.

Yours faithfully,
Sgt 3
Sharon Ye Jiahui
Investigation Officer (GIT B)
Traffic Police
Singapore Police Force

This is a computer-generated letter. No signature is required.

A FORCE FOR THE NATION



SINGAPORE POLICE FORCE



T/20240516/7020

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20240516/7020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/05/2024 10:18		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MUHAMMAD FAIZAL BIN BAHARIN			Address: 226 PASIR RIS STREET 21 #06-84 SINGAPORE 510226		
ID Type / ID No.: NRIC NO / S7938710Z			Contact No.: Home/Office: Mobile: 91997141		
Nationality: SINGAPORE CITIZEN			Email: muhammad_faizal_baharin@cnb.gov.sg		
Sex: Male	Age: 44	Date of Birth: 08/12/1979	Type of Informant: Supervisor to rider involved in accident		
Race: Malay			Language: English		
Occupation: Narcotics officer			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/05/2024 19:20	Type of Location: Straight Road
Location: UPPER THOMSON ROAD				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBW939Y	Motorcycle	YAMAHA	XMax	Black	Seriously Damaged	0
	Taxi					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20240516/7020

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20240516/7020

CONTINUATION OF REPORT

Rider			
Name	LIM CHEE HENG JIMMY	ID No.	S7539340G
Related Vehicle	FBW939Y (Motorcycle)	Contact No.	NIL
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	11/05/2024	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	Serious
Supervisor to rider involved in accident			
Name	MUHAMMAD FAIZAL BIN BAHARIN	ID No.	S7938710Z
Related Vehicle	NIL	Contact No.	91997141
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

(The details was provided by the rider of the said vehicle who is currently warded due to injuries)

On the said date at about the said time, I (Lim Chee Heng Jimmy of NRIC: S7539340G) was riding a government vehicle FBW939Y along Upper Thomson Road towards 1200 Upper Thomson Road Shell station on the 4th lane which is the extreme left lane. I was on official duty at that point of time and is officially permitted to ride the said motorcycle.

I do not remember what happen after that and only realised that I was laying on the hospital bed.



**SINGAPORE
POLICE FORCE**



T/20240516/7020

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20240516/7020

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MOHAMED SUFIAN BIN MOHAMED JUNID
Contact No.: 65476247

Signature Of Informant:
The identity of the person making this report has been
authenticated by Singpass. No signature is required.

Date/Time:
16/05/2024 10:18

Classification Of Case:

NP168

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SHA4573L

Date of Accident

11/05/2024 𠂇

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance MS First Capital Insurance Ltd

Period of Insurance 01/01/2024 - 31/12/2024

Requested By Tan Chok Lok (Ban Hock Hin C...

Requested Date 28/08/2024 10:07

Payment details

Request Amount: S\$2

GST Amount: S\$0.18

Total Amount Due (GST Inclusive): S\$2.18

General Insurance Association

Records Management Centre

GST Registration No: M400017735