

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921
 Email: ryderautoworkshop@gmail.com
 Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# XE5127A

Model: ISUZU CYZ52R
 5/9/2019

Accident Date :24/8/2024

Location : TUAS SOUTH STREET 5

3P: SLN3541U (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front Rh step garnish upper bracket	320.60	✓	
2	1 pc	Front bumper RH head lamp garnish	110.00	✓	
3	1 pc	Front Rh door garnish	650.00	✓	
4	1 pc	Front Rh door garnish bracket	220.50	✓	
5	1 pc	Front Rh door garnish bracket clips		120.00	20
Sub Total:			1,301.10	120.00	0.00
			10%	15%	0%
After Less %:			1,170.99	120.00	0.00
Total:				1,290.99	
After Less 20%:				1,032.79	

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

Adrian Ls
fl.s



8778 1999
 24 hr accident call



1301.10

1105.93

S.N: 20

Supplementary 1125.93.