

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TP INC
Hui Rong
TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR DUCT <i>new</i>	1	127.50	<i>+</i> 127.50
BATTERY TRAY <i>new</i>	1	90.00	<i>+</i> 90.00
ENGINE ECU <i>included</i>	1	1890.00	<i>-</i> 1,890.00
FRONT AIRCON CONDENSER <i>wrapped</i>	1	568.10	<i>-</i> 568.10
FRONT BONNET <i>Distorted</i>	1	892.30	<i>-</i> 892.30
FRONT BONNET HINGES L/R <i>Best</i>	2	48.50	<i>-</i> 97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	23.80	<i>+</i> 47.60
FRONT BONNET INNER SIDE MOULDING L/R <i>lit out</i>	2	37.50	<i>37.50</i> 75.00
FRONT BONNET INNER TOP MOULDING L/R <i>new</i>	2	23.00	<i>+</i> 46.00
FRONT BONNET INSULATOR <i>cracked</i>	1	122.30	<i>-</i> 122.30
FRONT BONNET MECHANISM LOCK <i>new</i>	1	95.00	<i>+</i> 95.00
FRONT BUMPER <i>Missing</i>	1	801.70	<i>-</i> 801.70
FRONT BUMPER FOGLAMP BRACKET L/R <i>Missing</i>	2	75.00	<i>-</i> 150.00
FRONT BUMPER FOGLAMP GARNISH L/R <i>Missing</i>	2	45.00	<i>-</i> 90.00
FRONT BUMPER FOGLAMP L/R <i>missing</i>	2	269.00	<i>-</i> 538.00
FRONT BUMPER LOWER GRILLE <i>new</i>	1	77.50	<i>+</i> 77.50
FRONT BUMPER LOWER LID <i>Delivered</i>	1	381.00	<i>-</i> 381.00
FRONT BUMPER LOWER LID SPOILER <i>new</i>	1	138.00	<i>+</i> 138.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

Contact : 82336734

FRONT BUMPER REINFORCEMENT	<i>Deled</i>	1	321.00	✓	321.00
FRONT BUMPER SIDE RETAINER L/R	<i>Lit could</i>	2	20.60	<i>20.60</i>	<i>41.20</i>
FRONT BUMPER TOW HOOK COVER	<i>Missing</i>	1	17.10	✓	17.10
FRONT FENDER 'HYBRID' EMBLEM L/R	<i>LH xhu</i>	2	58.00	<i>58</i>	<i>116.00</i>
FRONT FENDER ARCH GARNISH L/R	<i>LH Missing, RH could</i>	2	220.00	✓	440.00
FRONT FENDER L/R	<i>LH Disturbed</i>	2	580.00	<i>580</i>	<i>1,160.00</i>
FRONT GRILLE	<i>Missing</i>	1	351.80	✓	351.80
FRONT GRILLE 'LOGO' EMBLEM	<i>Missing</i>	1	23.40	✓	23.40
FRONT GRILLE CENTER BRACKET		1	76.00	✓	76.00
FRONT GRILLE CHROME MOULDING		1	98.00	✓	98.00
FRONT GRILLE OUTER COVER		1	421.00	✓	421.00
FRONT GRILLE TOP GARNISH		1	85.00	✓	85.00
FRONT HEADLAMP L/R	<i>LH Smashed, RH could</i>	2	1784.50	<i>1784.50</i>	<i>3569.00</i> ✓
FRONT HEADLAMP LOWER BRACKET L/R	<i>LH Smashed, RH could</i>	2	35.00	<i>35</i>	<i>70.00</i> ✓
FRONT HEADLAMP SIDE BRACKET L/R	<i>LH Smashed, RH could</i>	2	35.00	<i>35</i>	<i>70.00</i> ✓
FRONT HORN	<i>xhu</i>	1	110.50	✓	110.50
FRONT LH CHASSIS SIDE MEMBER (LOWER)	<i>Disturbed</i>	1	65.00	✓	65.00
FRONT LH CHASSIS SIDE MEMBER (TOP)		1	98.00	✓	98.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

Contact : 82336734

FRONT LH DOOR	Repr	1	910.20	+	910.20
FRONT LH DOOR BLACK TAPE	new	1	26.40	+	26.40
FRONT LH DOOR GLASS OUTER MOULDING	new	1	28.60	+	28.60
FRONT LH DOOR MECHANISM LOCK	new	1	221.70	+	221.70
FRONT LH FENDER INNER ARCH PANEL	Buckled	1	298.00	✓	298.00
FRONT LH FENDER INNER BRACKET	Best	1	75.00	✓	75.00
FRONT LH FENDER INNER PANEL	Distorted	1	198.00	✓	198.00
FRONT LH FENDER INNER SHIELD	torn	1	125.00	✓	125.00
FRONT LH FUSO BOX ASSY	crushed	1	1890.00	✓	1,890.00
FRONT OUTSIDE TEMPERATURE SENSOR	new	1	80.00	+	80.00
FRONT RADIATOR SPARE TANK	new	1	120.30	+	120.30
FRONT SUPPORT PANEL	Buckled	1	576.20	✓	576.20
FRONT WIPER GARNISH	new	1	205.00	+	205.00
RADIATOR (AUTO)	Distorted	1	1376.60	✓	1,376.60
RADIATOR SIDE GUIDE L/R	new LH Distorted	2	31.60	31.60	63.20
REAR AXLE	Best	1	1685.20	✓	1,685.20
REAR BODY EXTENSION LH	Distorted	1	720.00	✓	720.00
REAR BODY EXTENSION UPPER PANEL LH	Distorted	1	160.00	✓	160.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

REAR BUMPER	<i>Disturbed</i>	1	762.70	✓	762.70
REAR BUMPER LOWER COVER	<i>Disturbed</i>	1	250.00	✓	250.00
REAR BUMPER REFLECTOR L/R	<i>LH Missing</i>	2	141.10	<i>141.10</i>	282.20
REAR BUMPER SIDE L/R	<i>LH Missing</i>	2	195.00	<i>195</i>	390.00
REAR BUMPER SIDE RETAINER L/R	<i>LH Smashed</i>	2	23.00	<i>23</i>	46.00
REAR END PANEL	<i>Disturbed</i>	1	415.60	✓	415.60
REAR END PANEL INNER TOP GARNISH	<i>Disturbed</i>	1	98.00	✓	98.00
REAR FLOOR PANEL	<i>Disturbed</i>	1	662.20	+	662.20
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	<i>Disturbed</i>	1	485.30	✓	485.30
REAR FLOOR PANEL INNER TOP BOARD COVER	<i>Disturbed</i>	1	430.30	✓	<i>295</i> 430.30
REAR LH DOOR	<i>Disturbed</i>	1	883.40	✓	883.40
REAR LH DOOR BLACK TAPE	<i>Disturbed</i>	1	29.80	✓	29.80
REAR LH DOOR CHECKER	<i>Disturbed</i>	1	50.40	✓	50.40
REAR LH DOOR GLASS OUTER MOULDING	<i>Disturbed</i>	1	30.40	✓	30.40
REAR LH DOOR GLASS REGULATOR WITH MOTOR	<i>Disturbed</i>	1	412.50	✓	412.50
REAR LH DOOR HINGE (LOWER)	<i>Disturbed</i>	1	49.20	✓	49.20
REAR LH DOOR HINGE (TOP)	<i>Disturbed</i>	1	49.20	✓	49.20
REAR LH DOOR INNER TRIM BOARD	<i>Disturbed</i>	1	499.80	✓	499.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

REAR LH DOOR LOCK STRIKER	<i>Here Dnd</i>	1	39.80	<i>✓</i>	39.80
REAR LH DOOR MECHANISM LOCK	<i>Jammed</i>	1	299.70	<i>✓</i>	299.70
REAR LH DOOR OUTER HANDLE	<i>Dnd</i>	1	93.70	<i>✓</i>	93.70
REAR LH DOOR WEATHER STRIP	<i>} torn</i>	1	149.20	<i>✓</i>	149.20
REAR LH DOOR WEATHER STRIP LOWER		1	29.20	<i>✓</i>	29.20
REAR LH DOOR WEATHER STRIP VERTICAL		1	39.40	<i>✓</i>	39.40
REAR LH FENDER	<i>Distorted</i>	1	790.20	<i>✓</i>	790.20
REAR LH FENDER ARCH GARNISH	<i>Distorted</i>	1	195.00	<i>✓</i>	195.00
REAR LH FENDER INNER AIR VENT	<i>Smashed</i>	1	30.30	<i>✓</i>	30.30
REAR LH FENDER INNER PANEL	<i>Distorted</i>	1	505.00	<i>✓</i>	505.00
REAR LH FENDER INNER SHIELD	<i>torn</i>	1	147.50	<i>✓</i>	147.50
REAR LH FENDER INNER TOP GARNISH	<i>Distorted</i>	1	392.40	<i>240</i> <i>✓</i>	<i>392.40</i>
REAR LH FENDER INNER TRIM GARNISH	<i>Distorted</i>	1	295.00	<i>✓</i>	295.00
REAR LH FENDER INNER WHEEL HOUSING	<i>Distorted</i>	1	429.80	<i>✓</i>	429.80
REAR LH FENDER OUTER GARNISH	<i>Distorted</i>	1	191.20	<i>✓</i>	191.20
REAR LH FENDER PETROL CAP	<i>} Distorted</i>	1	79.80	<i>✓</i>	79.80
REAR LH FENDER PETROL LID		1	99.40	<i>✓</i>	99.40
REAR LH FENDER PETROL LOCK		1	39.40	<i>✓</i>	39.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

REAR LH FENDER PETROL PIPE	<i>Replaced</i>	1	129.80	✓	129.80
REAR LH SHOCK ABSORBER	<i>Best</i>	1	285.40	✓	285.40
REAR LH SPORT RIM	<i>new set</i>	1	878.50	<i>4x4 (500)</i> +	878.50
REAR LH TAILLAMP INNER PANEL	<i>3 Distorted</i>	1	278.00	✓	278.00
REAR LH TAILLAMP INNER VERTICAL PANEL		1	79.20	✓	79.20
REAR LH WHEEL BEARING	<i>Damaged</i>	1	328.40	✓	328.40
REAR TAILGATE	<i>Replaced</i>	1	953.30	✓	953.30
REAR TAILGATE 'HYBRID' EMBLEM	<i>3 new</i>	1	75.80	✓	75.80
REAR TAILGATE 'VEZEL' EMBLEM		1	56.20	✓	56.20
REAR TAILGATE DAMPER L/R	<i>LH Rnd</i>	2	180.00	<i>180</i>	360.00
REAR TAILGATE HINGES L/R	<i>LH Best</i>	2	50.00	<i>50</i>	100.00
REAR TAILGATE INNER PULL GARNISH	<i>new</i>	1	27.50	+	27.50
REAR TAILGATE INNER TRIM GARNISH	<i>Replaced</i>	1	153.40	✓	153.40
REAR TAILGATE MECHANISM LOCK	<i>Replaced</i>	1	180.00	✓	180.00
REAR TAILGATE MECHANISM LOCK STRIKER	<i>new</i>	1	27.50	+	27.50
REAR TAILGATE OUTER GARNISH	<i>Replaced</i>	1	220.00	✓	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	<i>new</i>	1	25.00	✓	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	<i>LH new</i>	2	38.50	<i>38.50</i>	77.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

REAR TAILGATE REFLECTOR L/R	LN Smashed	2	413.20	413.20	826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R	new	2	18.50	+	37.00
REAR TAILGATE TOP SPOILER	crack	1	593.60	✓	593.60
REAR TAILGATE WEATHER STRIP	tear	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN	shattered	1	129.40	✓	129.40
REAR TAILGATE WINDSCREEN INNER SEAL	new	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN INNER SIDE GARNISH LH	Missing	1	69.40	✓	69.40
REAR TAILGATE WINDSCREEN MOULDING	new	2	50.00	✓	100.00
REAR TAILLAMP L/R	LN Smashed	2	474.60	474.60	949.20
ROCKER GARNISH LH	crack	1	412.70	✓	412.70
ROOF TOP TRIM UPHOLSTERY	new	1	1015.00	2/4	1,015.00

Subtotal before discount

40,356.90

Percentage discount 20%

8,071.38

Sub-total 1

32,285.52

BATTERY	new	1	300.00	+	300.00
FRONT BONNET INSULATOR CLIPS - SET	new	1	60.00	30	60.00
FRONT BUMPER CLIPS - SET	new	1	50.00	30	50.00
FRONT FENDER ARCH GARNISH CLIPS L/R - SET	new	2	30.00	40	60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

FRONT GRILLE CLIPS - SET <i>new</i>	1	50.00	30	50.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	40.00	30	40.00
FRONT NUMBER PLATE	1	25.00	✓	25.00
FRONT NUMBER PLATE HOLDER <i>Missing</i>	1	50.00	30	50.00
FRONT WIPER GARNISH CLIPS - SET <i>new</i>	1	50.00	+	50.00
RADIATOR COOLANT <i>new</i>	1	80.00	40	80.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET <i>Brand</i>	1	350.00	200	350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	20	30.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new</i>	2	40.00	20	80.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	30	60.00
REAR FLOOR PANEL INSULATOR MAT <i>new</i>	1	300.00	+	300.00
REAR HYBRID INVERTER REMOVE, REINSTALL & REPROGRAM SYSTEM	1	1600.00	480	1,600.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR LH FENDER INNER TOP GARNISH CLIPS - SET <i>new</i>	1	50.00	20	50.00
REAR LH TYRE <i>lit</i>	1	500.00	180	500.00
REAR NUMBER PLATE <i>new</i>	1	25.00	+	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

REAR NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	40.00	40.00
REAR TAILGATE REVERSE CAMERA	1	800.00	800.00
REAR TAILGATE SPOILER CLIPS - SET	1	50.00	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	60.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	60.00
ROCKER GARNISH LH CLIPS - SET	1	50.00	50.00
Subtotal before discount			5,070.00
Percentage discount 0%			0.00
Sub-total 2			5,070.00
Parts-total			37,355.52

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

60 150.00
30 80.00
✓ 80.00
120 150.00
280 350.00
80 100.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 82336734

TAX INVOICE

Repair Code : CLM16407

Date in : 27/08/2024

Vehicle Num. : SLT3843S

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261759/LEB5961776

To remove, reinstall petrol tank. (to FR)

60 80.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80 120.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

60 160.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel, rear bumper, rear doors (L/R), and roof top panel.

1000 1,600.00

To re-spray painting on the front bonnet, front support panel, front fender (L/R), front bumper and front doors (L/R).

6180

1200 1,700.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

3000 4,000.00

To apply anti-rust chemical on repaired and replaced panel.

150 280.00

To remove, reinstall tailgate mechanism and check for function

60 80.00

Labour Total


8,930.00

Parts & Labour Total

46,285.52

*** This is a computer-generated document which requires no signature.***

page 10



Akhin S
2/s. 28/08/24.
24 Days.
Supplementary: 1513.60
Total: 35925.88
L/S: 26K ✓
(Nett Value)

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

TWINCAR LEASING PTE LTD

2 KAKI BUKIT AVE 2 #01-17

KAKI BUKIT AUTOHUB

SINGAPORE 417921

Repair Code: CLM16407

Date in: 26/08/2024

Vehicle No.: SLT3843S

Model: HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng#: RU31261759/LEB5961776

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	FRONT LH SHOCK ABSORBER <i>Best</i>	L	1	\$ 345.00	\$ 345.00
2	FRONT LH LOWER ARM <i>Best</i>	L	1	\$ 345.00	\$ 345.00
3	FRONT LH KNUCKLE ARM <i>Best</i>	L	1	\$ 486.00	\$ 486.00
4	FRONT LH KNUCKLE ARM BEARING <i>Best</i>	L	1	\$ 205.00	\$ 205.00
5	FRONT LH ALARM SIREN <i>5 months</i>	L	1	\$ 198.00	\$ 198.00
6	FRONT LH SMALL FUSE BOX <i>New</i>	L	1	\$ 125.00	\$ 125.00
7	FRONT LH RESONATOR <i>original</i>	L	1	\$ 115.00	\$ 115.00
Sub total 1: before discount:					\$ 1,819.00
Percentage discount 20%:					\$ 363.80
Sub-total 2: after discount:					\$ 1,455.20
8	FRONT LH TYRE <i>New</i>	S	1	\$ 500.00	\$ 500.00
Sub-total 3 :					\$ 500.00
Parts Total:					\$ 1,955.20

Rear LH door pillar weather strip

at

198.00 ✓

Adrian Cj
2/5 30/08/24

1892

1513.60