

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	26-08-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SNJ3019J
MAKE & MODEL:	HONDA FREED
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	24 August, 2024
TIME:	1500HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 1,530.20	\$ 1,530.20
2	TAIL GATE LOGO	1	\$ 90.00	\$ 90.00
3	TAIL GATE FREED EMBLEM	1	\$ 85.00	\$ 85.00
4	TAIL GATE HYBRID EMBLEM	1	\$ 80.00	\$ 80.00
5	TAIL GATE HINGE <i>new</i>	2	\$ 95.00	\$ 190.00
6	TAIL GATE DAMPER <i>new</i>	2	\$ 160.00	\$ 320.00
7	TAIL GATE INNER HANDLE <i>Defunct</i>	1	\$ 90.00	\$ 90.00
8	TAIL GATE INNER TRIM BOARD <i>cracked</i>	1	\$ 480.00	\$ 480.00
9	TAIL GATE LOCK <i>Failed</i>	1	\$ 280.00	\$ 280.00
10	TAIL GATE WEATHERSTRIP <i>let</i>	1	\$ 290.00	\$ 290.00
11	TAIL GATE LAMP <i>cracked</i>	2	\$ 420.00	\$ 840.00
12	TAIL GATE ANTENNA <i>new</i>	1	\$ 185.00	\$ 185.00
13	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 195.20	\$ 195.20
14	TAIL GATE WIPER BLADE MOTOR <i>new</i>	1	\$ 450.00	\$ 450.00
15	NUMBER PLATE LAMP CHROME <i>cracked</i>	1	\$ 380.00	\$ 380.00
16	NUMBER PLATE LAMP <i>new</i>	2	\$ 90.00	\$ 180.00
17	REAR BUMPER <i>Defunct</i>	1	\$ 1,155.20	\$ 1,155.20
18	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
19	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 90.00	\$ 180.00
20	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 80.00	\$ 80.00
21	REAR BUMPER PARKING SENSOR <i>new</i>	2	\$ 280.00	\$ 560.00

200(SN)

22	TAILLAMP <i>LH cut, RH cancelled</i>	2	\$ 655.30	\$ 1,310.60	✓
23	REAR FENDER INNER TRIM BOARD <i>RH cancelled</i>	2	\$ 680.00	\$ 1,360.00	680
24	REAR END PANEL <i>Dented</i>	1	\$ 680.00	\$ 680.00	✓
25	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 195.00	\$ 195.00	✓
26	REAR FLOOR PANEL <i>Reps</i>	1	\$ 1,355.80	\$ 1,355.80	+
27	REAR FLOOR PANEL TOP MAT <i>Not in</i>	1	\$ 1,050.30	\$ 1,050.30	+

TOTAL PRICE \$ 13,717.10

LESS 20% \$ 2,743.42

SUB TOTAL PRICE \$ 10,973.68

6688.96

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR NUMBER PLATE <i>Cancelled</i>	1	\$ 50.00	\$ 50.00	✓
2	TAILGATE WINDSCREEN SEALANT <i>Not in</i>	1	\$ 120.00	\$ 120.00	60
3	TAILGATE INNER TRIM CLIPS SET <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
4	NUMBER PLATE CHROME CLIPS(SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
5	REAR BUMPER CLIPS SET <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
6	TAILLAMP CLIPS(SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	X
7	REAR FENDER INNER TRIM CLIPS SET <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
8	REAR END PANEL TOP GARNISH CLIPS SET <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
9	REAR END PANEL INSULATION SEALANT <i>Not in</i>	1	\$ 120.00	\$ 120.00	60.
10	REAR FLOOR PANEL INSULATION SEALANT <i>Not in</i>	1	\$ 120.00	\$ 120.00	X

rear bumper PARKING SENSOR - 200

TOTAL \$ 530.00

470

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,800.00	\$ 1,800.00	1000.
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,800.00	\$ 1,800.00	800
3	TUFF COAT	1	\$ 200.00	\$ 200.00	60
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	50
8	TRANSFER TAILGATE MECHANISM	1	\$ 100.00	\$ 100.00	60
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 140.00	\$ 140.00	120

TOTAL \$ 4,600.00

2230

ESTIMATE REPORT

TOTAL PARTS COST	\$	11,503.68
TOTAL LABOUR COST	\$	4,600.00
TOTAL REPAIR COST	\$	16,103.68

APPROVED DETAILS:

SURVEYOR:
 CONTACT NO.:
 PART BY PART/LUMP SUM
 NO. OF DAYS

Adrian Ly
 2/5 28/08/24
 07 Days.

6688.96
 + 4700.00
 - 2230.00

 9388.96
 - 20% 1877.792

 7511.168

Lump Sum 57500 & 70 days.