

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

HIC
Kenneth
18/06/24

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

15/05/2024

Owner: ANG CHIN KENG

Not Authorised
C1 Rep @ 2500/-
Running After Pains
04 days

ESTIMATE TO REPAIR TOYOTA LEXUS ES250 - SMW2177K

1pc	rear boot cover		R	\$ 1,850.50	X
1pc	rear boot cover "LEXUS" emblem	98.90	M	\$ 121.50	—
1pc	rear boot cover "ES250" emblem	96.20	M	\$ 118.20	—
1pc	rear bumper	1280	Bu	\$ 1,350.50	—
2pcs	rear bumper side retainer @\$132.25		SL	\$ 264.50	X
1pc	rear bumper lower garnish		MB	\$ 381.50	—
1pc	rear bumper lower garnish chrome		M	\$ 181.20	—
2pcs	rear bumper lower garnish side chrome @\$158.50		SL	\$ 317.00	X
2pcs	rear bumper centre parking sensor @\$281.50		SL	\$ 563.00	X
1pc	rear bumper reinforcement		Bu	\$ 385.20	—
1pc	rear bumper sponge		CM	\$ 195.20	—
1pc	rear end panel		R	\$ 781.50	X
1pc	rear end panel inner garnish		SL	\$ 481.20	X
				\$ 6,991.00	
less 25%				\$ 1,747.75	
				\$ 5,243.25	

1set rear number plate & casing

s.nett \$SL 50.00 X

wiring
tuffkote
spray painting
labour charges
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 80.00 15/
\$ 80.00 X
\$ 1,200.00 660/
\$ 1,200.00 500/
\$ 7,853.25

