

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

17/6
Korath
18/06/24

15/05/2024

Owner: ANG CHIN KENG

Not Autho
C/Ly @
Penny Aft Rainy

ESTIMATE TO REPAIR TOYOTA LEXUS ES250 - SMW2177K

1pc	rear boot cover	R	\$ 1,850.50	X
1pc	rear boot cover "LEXUS" emblem	M	\$ 121.50	—
1pc	rear boot cover "ES250" emblem	M	\$ 118.20	—
1pc	rear bumper	Bu	\$ 1,350.50	—
2pcs	rear bumper side retainer @\$132.25	Sm	\$ 264.50	X
1pc	rear bumper lower garnish		\$ 381.50	7
1pc	rear bumper lower garnish chrome		\$ 181.20	7
2pcs	rear bumper lower garnish side chrome @\$158.50	Sm	\$ 317.00	X
2pcs	rear bumper centre parking sensor @\$281.50	Sm	\$ 563.00	X
1pc	rear bumper reinforcement		\$ 385.20	7
1pc	rear bumper sponge		\$ 195.20	7
1pc	rear end panel	R	\$ 781.50	X
1pc	rear end panel inner garnish	Sm	\$ 481.20	X
			\$ 6,991.00	
less 25%			\$ 1,747.75	
			\$ 5,243.25	

1set rear number plate & casing

s.nett \$ 50.00 X

wiring
tuffkote
spray painting
labour charges
Total

\$ 80.00 15/2
\$ 80.00 7
\$ 1,200.00 4401
\$ 1,200.00 4001
\$ 7,853.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

