

PRECISE AUTO SERVICE
 NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883
 TEL : 67457367 FAX : 68413390
 CO. REG. NO.: 35766600C GST REG. NO.: 35766600C

*not Authorized
in
name
21/10/24
2/s \$4000
5 days
telephone follow up*

11-12-24

Date Of Accident : 25-08-24

Attn: Mr. Marcus

OUR REF : GBE 2733E/T/24

Ninja Logistics Pte Ltd
 3 Kay Siang Road

Date in/out: 21/10/24 to 25/10/24

Singapore 248923

ESTIMATE BILL ON VEH. NO. : GBE 2733E
VEH. MODEL : TOYOTA HIACE
CHASSIS NO : KDH2010176045

LIST ITEM

Tail Gate	<i>DD/Seat</i>		2,162.25	✓
Tail Gate Weatherstripe	<i>twl</i>		291.40	✓
Tail Gate Lock	<i>su</i>		371.25	X
Tail Gate Side Stopper "Male"	<i>11</i>	2pcs @ 43.75	87.50	X
Tail Gate Side Stopper "Female"	<i>11</i>	2pcs @ 43.10	86.20	X
Tail Gate Badge	<i>111</i>		121.10	✓
Tail Gate Rubber Stopper LH	<i>11</i>		121.70	X
Tail Gate Lock Motor	<i>11</i>		781.25	X
Rear Windscreen Glass Inner Seal	<i>111</i>		50.00	<i>20 S/N</i>
Rear Cornel Panel LH	<i>twl</i>		174.45	✓
Rear Cornel Panel Bracket	<i>cro</i>		127.25	✓
Rear Bumper	<i>DD</i>		371.70	✓
Rear Bumper Step Bracket	<i>311</i>		121.10	✓
Rear Bumper Side Retainer	<i>MS cro</i>	2pcs @ 172.25	344.50	<i>1 pc</i>
Rear Bumper Lower Bracket	<i>R</i>	3pcs @ 171.25	342.50	X
Rear End Panel (Outer)	<i>DD/Seat</i>		371.85	✓
Rear End Panel (Inner)	<i>R</i>		781.10	X

6,707.10

Less Discount 25%:

1,676.78

5,030.33

NETT ITEM

Rear Windscreen Glass Clips

14pcs @ 4.00 17 56.00 X

Rear Bumper Clips

10pcs @ 4.00 10 40.00 305/N

96.00

Less Discount 10%: 9.60

86.40

SPECIAL NETT ITEM

Tail Gate Advertisement Sticker

11 180.00 100

70km/h Sticker

11 20.00 10

Rear Windscreen Glass Sealant

11 60.00 40

Reverse Sensor

11 380.00 200

LABOUR CHARGE

Towing

11 100.00 X

To check wiring system

80.00 20

To remove & refix rear windscreen glass

180.00 120

To tuff coat affected areas

180.00 50

To remove & refix reverse sensor

120.00 30

To remove & refix tail gate mechanism

220.00 60

To respray affected areas

1,000.00 800

To renew damaged parts, straighten & repair and aligned all parts

1,000.00 600

8,636.73

GST 9%: 777.31

TOTAL AMOUNT: 9,414.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3913-38
252
2935.02
400
1680
5015.02
252
40.2