

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

7P mslg
Ati Rong

VEHICLE NO : SLQ4401T
CHASSIS NO : RU11205272

MAKE / MODEL : HONDA VEZEL
ACCIDENT DATE : 27.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Rear bumper <i>Delud</i>	1	\$ 636.18 ✓
2	Rear bumper LH reflector <i>At</i>	1	\$ 196.42 ✓
3	Rear bumper reverse sensor <i>new</i>	1	\$ 380.00 +
4	Rear bumper LH side holder <i>new</i>	1	\$ 20.93 +
5	Rear LH lamp <i>At</i>	1	\$ 475 576.03 ✓
6	Rear LH lamp lower garnish <i>Delud</i>	1	\$ 186.41 ✓
7	Rear LH fender side garnish <i>new</i>	1	\$ 176.18 +
8	Rear tailgate <i>RX</i>	1	\$ 1266.03 +
9	Rear tailgate VEZEL emblem <i>new</i>	1	\$ 55.77 ✓
10	Rear tailgate H logo <i>new</i>	1	\$ 27.48 +
11	Rear LH sport rim <i>At</i>	1	\$ 700 584.51 ✓
12	Rear LH tyre <i>new</i>	1	\$ 437.00 +
			\$ 4942.94
LESS 20% DISC			\$ 988.588
TOTAL			\$ 3954.35

1549.78
1239.82 SN: 400

LABOUR COST			
1	Remove, reinstall reverse sensor	1	\$ 150.00 50
2	Remove, replace + repair consistent to the accident	1	\$ 900.00 200
3	Respray painting	1	\$ 1000.00 300
TOTAL			\$ 2050.00
GRAND TOTAL			\$ 6004.35

550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adam Lj
s/s 29/08/24
03 2y

total: 2189.82

y/s: 1.7K ✓