

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 20 Sep 2024

Preliminary Advice

Insured Vehicle No	: FBN1964P	Accident Date	: 27/08/2024
TP Vehicle No	: SLQ4401T	Assignment Date	: 29/08/2024
Make	: HONDA VEZEL	Est. Duration of Repair	: 3
Date of Inspection	: 29/08/2024		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-61 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,004.35
Revised Amount	:S\$	2,189.82
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,189.82
Lump Sum Repair	:S\$	1,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.