

ASS. REC. BY:

REF: 0121

## ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

18.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

BRR 186

Yr Regn:

11, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Testa model 3

C.C.

Colour

mp. white

A/C: Insured / Std / NI / NA

Sp. Reading

18787

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LRW3F7IFS3RC008350Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

235/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/8/24

D.O.I.

9/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ - RS. SI

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 06/09/2024  
Vehicle No: BRR186  
Model: TESLA MODEL 3  
Chassis: LRW3F7FS3RC006350-2023  
Reg. Year: 20243

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLC4143L  
Date of Accident: 10/08/2024  
Estimator: TING AN  
Surveyor:

*Not Notion*  
*Runway B4 pain*  
*4 days*

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		<i>B</i> \$893.62 ✓
2	REAR BOOTLID LOCK	1		<i>R</i> \$54.20 X
3	REAR BOOTLID WEATHSTRIP	1		<i>R</i> \$124.11 X
4	REAR BOOTLID TRIM BOARD	1		\$43.02 7
5	REAR BOOTLID "TESLA" EMBLEM	1		<i>m</i> \$41.37 ✓
6	REAR BUMPER	1		<i>BX/UM</i> \$696.16 ✓
7	REAR BUMPER REINFORCEMENT	1		\$271.03 7
8	REAR BUMPER CENTER BRACKET	1		\$49.48 7
9	REAR BUMPER LOWER LIP	1		<i>Red</i> \$215.48 ✓
10	REAR BUMPER LAMP LH	1		<i>CM</i> \$356.37 7
11	REAR END PANEL UPPER COVER	1		\$21.18 7
12	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,766.02
LESS 10%				-\$276.60
PARTS TOTAL				\$2,489.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID TRIM BOARD CLIPS	1		\$50.00 7
2	REAR BUMPER CLIPS	1		<i>m</i> \$50.00 ✓
3	REAR NUMBER PLATE & HOLDER	1		<i>R</i> \$50.00 X
4	REAR END PANEL UPPER COVER CLIPS	1		<i>m</i> \$40.00 X
S/N TOTAL				\$40.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_ Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 06/09/2024  
Vehicle No: BRR186  
Model: TESLA MODEL 3  
Chassis: LRW3F7FS3RC006350-2023  
Reg.Year: 20243

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLC4143L  
Date of Accident: 10/08/2024  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	4001
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.	\$800.00	4401
LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOTLID INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR BOOTLID	\$120.00	601
TO DAIGNOSIS FAULT CODE & ETC.	\$250.00	7
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00	201

LABOUR TOTAL	\$2,320.00
--------------	------------

TING AN	TOTAL	\$4,849.42
---------	-------	------------

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011







# SINGAPORE POLICE FORCE



T/20240810/2062

1 of 3

Report No. T/20240810/2062

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
10/08/2024 19:06

Vide Report No.:  
G/20240810/0121

Station Diary No.:  
80

**Informant's Particulars**

Name of Informant:  
LOUIS CHUA MHIN KHIT

Address:  
86 JALAN PUTERI 8/10 BANDAR PUTERI PUCHONG  
SELANGOR SINGAPORE 047100

ID Type / ID No.:  
NEW MALAYSIAN IC /  
941009105453

Contact No.:  
Home/Office: Mobile: 60173363793

Nationality:  
MALAYSIAN

Email:

Sex:  
Male

Age:  
29

Date of Birth:  
09/10/1994

Type of Informant:  
Driver

Race:  
Chinese

Language:

Occupation:  
Sales manager

Driving Licence Information:  
Class: 3

Date of Expiry:

**General Information of the Accident**

Type of  
Accident:

Non-Injury  
Foreign Vehicle

Drink  
Drive:  
No

Date/Time of  
Accident:  
10/08/2024 16:10

Type of Location:  
Flyover

Location:

AIRPORT ROAD

Weather:

Road Surface:

Traffic Flow:

Traffic Control:

Traffic Volume:  
Heavy

Type of Collision:

Between Moving Vehicles - Head To Rear

Anyone conveyed by  
ambulance:  
No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Conditio	No of Passenger
BRR186	Motor car	TESLA	MODEL 3	White		1
SLC4143L	Motor car	HYUNDAI	ELANTRA AD 1.6 GLS AT	Blue		0



# SINGAPORE POLICE FORCE



T/20240810/2062

2 of 3

Report No. T/20240810/2062

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
<b>Driver</b>			
Name	LOUIS CHUA MHIN KHIT	ID No.	941009105453
Related Vehicle	BRR186 (Motor car)	Contact No.	60173363793
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

### Brief Details.

On 10/08/2024 at about 1610hrs, I was driving along KPE towards TPE, nearing to Paya Lebar exit, 4.3KM. I was on lane 2 and the traffic was heavy. The vehicle in front of me started to brake and slowed down, as such I followed. When the car in front came to a complete stop, I followed as well. However, when I stopped, the car behind hit on to me. We drove to the road shoulder, took photos, shortly after, auxiliary police and tow truck came. After awhile Traffic Police came to scene as well. I did not take down the particulars of the other party, but the Traffic Police had taken it.

I wish to state that no one was injured at the point of time. My car bumper paint are damaged and my car boot dented. The other car bonnet dented and his front grille damaged.