

ASS. REC. BY:

REF:

C4/CTZ 24080490/Kqj3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: BRR 186 Yr Regn: 11, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Testa model 3 c.c. _____Colour: mp. white A/C: Insured / Std / NI / NASp. Reading: 18787 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LRW3F7FS3RC008350Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 235/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 10/8/24 D.O.I. 9/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11 @ 3280.22 Cash (red @ 1589.20, 33%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trlp: 2

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

22 claims - TP
3280.22

Date: 06/09/2024
Vehicle No: BRR186
Model: TESLA MODEL 3
Chassis: LRW3F7FS3RC006350-2023
Reg.Year: 20243

Not Authorised
Running B4 pain
4 days
Q3260.22

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLC4143L
Date of Accident: 10/08/2024
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		<i>Bz</i> \$893.62 ✓
2	REAR BOOTLID LOCK	1		<i>R</i> \$54.20 X
3	REAR BOOTLID WEATHSTRIP	1		<i>R</i> \$124.11 X
4	REAR BOOTLID TRIM BOARD	1		<i>R</i> \$43.02 X
5	REAR BOOTLID "TESLA" EMBLEM	1		<i>R</i> \$41.37 ✓
6	REAR BUMPER	1		<i>Bx/CM</i> \$696.16 ✓
7	REAR BUMPER REINFORCEMENT	1		<i>Bu</i> \$271.03 ✓
8	REAR BUMPER CENTER BRACKET	1		<i>CM</i> \$49.48 ✓
9	REAR BUMPER LOWER LIP	1		<i>Pcl</i> \$215.48 ✓
10	REAR BUMPER LAMP LH	1		<i>CM</i> \$356.37 ✓
11	REAR END PANEL UPPER COVER	1		<i>mpm</i> \$21.18 ✓
12	REAR END PANEL	1		REPAIR ✓
SUB TOTAL				\$2,766.02
LESS 10%				-\$276.60
PARTS TOTAL				\$2,489.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID TRIM BOARD CLIPS	1		<i>NA</i> \$50.00 X
2	REAR BUMPER CLIPS	1		<i>R</i> \$50.00 ✓
3	REAR NUMBER PLATE & HOLDER	1		<i>R</i> \$50.00 X
4	REAR END PANEL UPPER COVER CLIPS	1		<i>NA</i> \$40.00 X
S/N TOTAL				\$40.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 06/09/2024
Vehicle No: BRR186
Model: TESLA MODEL 3
Chassis: LRW3F7FS3RC006350-2023
Reg.Year: 20243

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLC4143L
Date of Accident: 10/08/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,000.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.

\$800.00 *440*

LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOTLID INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR BOOTLID

\$120.00 *60*

TO DAIGNOSIS FAULT CODE & ETC.

nn \$250.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 *20*

LABOUR TOTAL \$2,320.00

TING AN

TOTAL

\$4,849.42