

Date: 06/09/2024

Vehicle No: BRR186

Model: TESLA MODEL 3

Chassis: LRW3F7FS3RC006350-2023

Reg.Year: 20243

Third Party Insurer: CHINA TAIPING

Third Party Veh No: SLC4143L

Date of Accident: 10/08/2024

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		R \$893.62
2	REAR BOOTLID LOCK	1		R \$54.20
3	REAR BOOTLID WEATHSTRIP	1		R \$124.11
4	REAR BOOTLID TRIM BOARD	1		R \$43.02
5	REAR BOOTLID "TESLA" EMBLEM	1		R \$41.37
6	REAR BUMPER	1		RX/CM \$696.16
7	REAR BUMPER REINFORCEMENT	1		R \$271.03
8	REAR BUMPER CENTER BRACKET	1		CM \$49.48
9	REAR BUMPER LOWER LIP	1		R \$215.48
10	REAR BUMPER LAMP LH	1		CM \$356.37
11	REAR END PANEL UPPER COVER	1		MX \$21.18
12	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,766.02
LESS 10%				-\$276.60
PARTS TOTAL				\$2,489.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID TRIM BOARD CLIPS	1		RM \$50.00
2	REAR BUMPER CLIPS	1		RM \$50.00
3	REAR NUMBER PLATE & HOLDER	1		R \$50.00
4	REAR END PANEL UPPER COVER CLIPS	1		RM \$40.00
S/N TOTAL				\$40.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 06/09/2024
Vehicle No: BRR186
Model: TESLA MODEL 3
Chassis: LRW3F7FS3RC006350-2023
Reg.Year: 20243

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLC4143L
Date of Accident: 10/08/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

4001
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.

\$800.00 4401

LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOTLID INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR BOOTLID

\$120.00 601

TO DAIGNOSIS FAULT CODE & ETC.

nn \$250.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 201

LABOUR TOTAL	\$2,320.00
--------------	------------

TING AN

TOTAL	\$4,849.42
-------	------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

