



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080494/Uvh3
75 BRAS BASAH ROAD	Date:	10/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 9748T	Veh. Inspected	SLQ 3838Z
Policy No.	-	Coverage	0
Claim No.	MT/1291881-002	Excess	\$0.00
Assign From	JULIE	Assign Date	28/08/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZR0A45319	Year of Reg.	19/12/2017
Chassis No.	MR053REH604576162	Colour	WHITE
Odometer	128754 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45ZR17	MATREX	6
L/H Front Tyre	215/45ZR17	MATREX	6
R/H Rear Tyre	215/45ZR17	MATREX	6
L/H Rear Tyre	215/45ZR17	MATREX	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/08/2024	Inspection Date	30/08/2024 (13:47)
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days