

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not authorized
du

30/08/24

4/5 @ \$5500

4 days

Wrephoto After repair

VEHICLE No: SLQ 3838Z

1PC	FRONT BUMPER	cur/ten	\$780.10	✓
1PC	FRONT BUMPER RETAINER N/S	sent	\$95.10	✓
1SET	FRONT BUMPER CLIPS	rec	\$40.00	✓
1PC	FRONT BUMPER REINFORCEMENT	na	\$450.10	X
1PC	FRONT BUMPER FOG LAMP N/S	see	\$281.20	X
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	cur/ten	\$128.90	✓
1PC	HEADLAMP N/S	see/cor	\$3,250.10	✓
1PC	FRONT FENDER N/S	cor/suf	\$755.10	✓
1PC	FRONT FENDER 'VVTI' EMBLEM N/S	rec	\$85.00	✓
1PC	FRONT FENDER INNER SHIELD N/S	na	\$198.10	X
1PC	FRONT FENDER INNER SHIELD CLIPS N/S	na	\$50.00	X
1PC	FRONT LOWER ARM N/S	cur/ten	\$689.10	✓
1PC	FRONT KNUCKLE ARM N/S	suf	\$554.20	✓
1PC	FRONT KNUCKLE ARM BEARING N/S	rec	\$368.00	✓
1PC	FRONT DRIVE SHAFT N/S	na	\$1,415.10	X
1PC	ROCKER PANEL GARNISH N/S	na	\$899.10	X
1PC	ROCKER PANEL N/S	na	\$912.80	X
			\$10,952.00	
			LESS 25%	\$8,214.00

S.NETT ITEM

1PC	FRONT SPORT RIM N/S	cur/ten	\$850.00	600
TO CHECK WIRING			\$50.00	20
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE			\$250.00	120
TO TRANSFER BOTH N/S DOOR MECHANISM			\$150.00	X
TO CONDUCT WHEEL ALIGNMENT			\$120.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$1,000.00	400
TO PUTTY & SPRAY PAINTING			\$1,680.00	600
TOTAL			\$12,314.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6745-6
252

5059.20

600

1220

6879.20

25

5503