



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)
ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675
ATTN: LAI PENGCHONG

Ref: CS3/SPF24080503/Avp3e2(N)

Date: 27/01/2025

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	TP 357A	Veh. Inspected	SMM 348A
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/043(LK)	Excess (\$)	0.00
Assign From	LAI PENGCHONG	Assign Date	29/08/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GB71075803	Colour	BLUE
Odometer	185514 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	FORTUNE	6 mm
L/H Front Tyre	185/65 R15	FORTUNE	6 mm
R/H Rear Tyre	185/65 R15	FORTUNE	6 mm
L/H Rear Tyre	185/65 R15	FORTUNE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/08/2024	Inspect Date / Time	27/08/2024 (01:08 PM)
Survey held at	INFINITY AUTO 57 PTE LTD 3020A UBI ROAD 1 #01-33 SINGAPORE 408714		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**