

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #01-77 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: NTUC INCOME	DATE	: 23/10/2024
VEHICLE NO	: SMP6993G (2019)	<i>Hui Rong</i>	
VEHICLE MODEL	: HONDA HRV		
CHASSIS NO	: JHMRU1830JX202144		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>tor</i>	1	\$ 545.60	\$ 545.60
2	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 23.40	\$ 23.40
3	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 321.80	\$ 321.80
4	FRONT BUMPER FOG LAMP <i>new</i>	1	\$ 327.70	\$ 327.70
5	FRONT BUMPER FOG LAMP COVER <i>new</i>	1	\$ 60.20	\$ 60.20
6	FRONT BUMPER LOWER GARNISH <i>new</i>	1	\$ 351.40	\$ 351.40
7	HEADLAMP <i>new</i>	1	\$ 1,859.40	\$ 1,859.40
8	HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 35.70	\$ 35.70
9	FRONT FENDER <i>Perked</i>	1	\$ 580.20	\$ 580.20
10	FRONT FENDER INNER SHIELD <i>tor</i>	1	\$ 134.10	\$ 134.10
11	FRONT FENDER ARC GARNISH <i>behind</i>	1	\$ 153.90	\$ 153.90
12	ROCKER PANEL OUTER SKIRTING <i>new</i>	1	\$ 415.30	\$ 415.30
13	FRONT SHOCK ABSORBER <i>new</i>	1	\$ 387.60	\$ 387.60
14	FRONT LOWER ARM <i>new</i>	1	\$ 405.70	\$ 405.70
15	FRONT KNUCKLE ARM <i>new</i>	1	\$ 398.40	\$ 398.40
16	FRONT WHEEL HUB C/W BEARING <i>new</i>	1	\$ 226.80	\$ 226.80

TOTAL PRICE: \$ 6,227.20
LESS 20% \$ 1,245.44
SUB TOTAL PRICE: \$ 4,981.76

1413.80

1131.04

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
2	FRONT FENDER INNER SHIELD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT FENDER ARC GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	ROCKER PANEL OUTER SKIRTING CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	FRONT WHEEL RIM <i>new</i>	1	\$ 850.00	\$ 850.00
6	FRONT TYRE <i>new</i>	1	\$ 280.00	\$ 280.00

TOTAL: \$ 1,240.00

80

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	800	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	30	
5	TO REMOVE FRONT UNDERCARRIAGE	\$ 350.00	+	
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	+	

TOTAL \$ 2,700.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,221.76

TOTAL LABOUR COST: \$ 2,700.00

TOTAL REPAIR COST: \$ 8,921.76

1360

total: 2371.04
L/S: 2050
0 4 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: