

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080505/UQP3M4**Date:** 10/09/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMV7575S **Insured Vehicle No :** SLS8891A

Date of Loss: 27/08/2024 Nature of Claim: TP Claim No: DMPC2401128H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV7575S**

Make & Model: BYD ATTO 3, (A) Engine No: HIDDEN

Reg. Date: 13/10/2022 (Man. Year: 2022) Chassis No: LGXCE4CB7N2081287

Colour: White Odometer: 29266 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55R18 Rear Tyre Size: 215/55R18

Front Left Side: Atlas 7 mm Rear Left Side: Atlas 7 mm

Front Right Side: Atlas 7 mm Rear Right Side: Atlas 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,310.95	4,950.00	6,360.95	56.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	890.00	1,280.00	58.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,480.95	5,840.00	7,640.95	56.68
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	13,480.95	4,600.00	8,880.95	65.88
+ GST 9.00/9.00% (S\$)	1,213.29	414.00	799.29	65.88
Nett Amount (S\$)	14,694.24	5,014.00	9,680.24	65.88

INSPECTION

Date of Assignment: 29/08/2024

Date Inspected: 29/08/2024 Inspected At: SPEEDWERKZ PRIVATE LIMITED
1 KAKI BUKIT AVENUE 6
#01-73 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2024)
Parts:	M1-SUV	BYD ATTO 3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV7575S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented/Bent	4,215.70 FL	*2,650.00 FL
2	1		*FRONT DOOR WEATHERSTRIPE LH	Not Necessary	210.80 FL	*- FL
3	1		*FRONT DOOR WINDOW GLASS OUTER MOULDING LH	Not Necessary	164.80 FL	*- FL
4	1		*FRONT DOOR LOWER BLACK GARNISH LH	Serviceable	368.80 FL	*- FL
5	1		*FRONT DOOR LOWER SILVER PROTECTOR LH	Cut/Deformed	329.10 FL	*260.00 FL
6	1		*FRONT DOOR INNER TRIMBOARD LH	Not Necessary	951.20 FL	*- FL
7	1		*REAR DOOR LH	Dented/Bent	4,088.90 FL	*2,350.00 FL
8	1		*REAR DOOR WEATHERSTRIPE LH	Not Necessary	210.80 FL	*- FL
9	1		*REAR DOOR WINDOW GLASS OUTER MOULDING LH	Not Necessary	164.80 FL	*- FL
10	1		*REAR DOOR LOWER BLACK GARNISH LH	Serviceable	368.80 FL	*- FL
11	1		*REAR DOOR LOWER SILVER PROTECTOR LH	Cut	329.10 FL	*240.00 FL
12	1		*REAR DOOR INNER TRIMBOARD LH	Not Necessary	942.70 FL	*- FL
13	1		*FRONT DOOR TRIMBOARD CLIPS RH	Not Necessary	100.00 FS	*- FS
14	1		*REAR DOOR TRIMBOARD CLIPS RH	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,545.50	5,500.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,234.55	550.00
Total Parts (S\$)	11,310.95	4,950.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT DOOR SIDE MIRROR RH	New	150.00	0.00
3	TO REMOVE AND TRANSFER FRONT RH DOOR FITTINGS }	New	120.00	120.00
4	TO REMOVE AND TRANSFER REAR RH DOOR FITTINGS }	New	120.00	0.00
5	TO PROVIDE LABOUR, WORKMANSHIP	New	800.00	200.00
6	TO SPRAY PAINT ON AFFECTED PANELS	New	800.00	500.00
7	RUST PROOFING	New	100.00	50.00
Gross Labour Cost (\$\$)			2,170.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >