

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

7P/INC
Hui Rong

VEHICLE NO : SLQ4401T
CHASSIS NO : RU11205272

MAKE / MODEL : HONDA VEZEL
ACCIDENT DATE : 27.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	Front LH fender <i>Dented</i>	1	\$ 573.27 ✓
2	Front LH fender side garnish <i>lit</i>	1	\$ 176.18 ✓
3	Front LH fender inner rear garnish <i>don</i>	1	\$ 67.73 ✓
4	Front LH fender inner shield <i>abe new</i>	1	\$ 149.73 X
5	Front LH door <i>Dented</i>	1	\$ 1092.73 ✓
6	Front LH door glass <i>lit</i>	1	\$ 741.40 ✓
7	Front LH door glass outer moulding <i>lit</i>	1	\$ 75.67 ✓
8	Front LH door handle <i>3 Damaged</i>	1	\$ 377.77 251 ✓
9	Front LH side mirror	1	\$ 862.73 ✓
10	Front LH side mirror housing <i>could</i>	1	\$ 94.87 ✓
11	Front LH door top hinge <i>3 NP</i>	1	\$ 63.94 X
12	Front LH door bottom hinge <i>3 NP</i>	1	\$ 61.87 X
13	Front LH door stopper <i>abe new</i>	1	\$ 32.77 X
14	Front LH door inner board <i>could</i>	1	\$ 782.34 525 ✓
15	Front LH door inner lower rubber <i>abe new</i>	1	\$ 21.04 X
16	Front LH door inner lock <i>Damaged</i>	1	\$ 265.07 ✓
17	Front LH door eye <i>3 NP</i>	1	\$ 28.75 X
18	Front LH door power window motor <i>3 NP</i>	1	\$ 478.97 X
19	Front LH door power window regulator <i>Damaged</i>	1	\$ 478.97 310 ✓
20	Front LH door speaker <i>abe new</i>	1	\$ 110.74 X
21	Front LH door sunrise visor <i>new</i>	1	\$ 80.00 60(SV) ✓
22	Front LH door frame black sticker <i>new</i>	1	\$ 37.37 ✓
23	Rear LH door <i>Dented</i>	1	\$ 1127.80 885 ✓
24	Rear LH door glass <i>lit</i>	1	\$ 724.61 450 ✓
25	Rear LH door glass outer moulding <i>lit</i>	1	\$ 75.09 ✓
26	Rear LH door top hinge <i>3 NP</i>	1	\$ 65.32 X
27	Rear LH door bottom hinge <i>3 NP</i>	1	\$ 63.59 X
28	Rear LH door stopper <i>abe new</i>	1	\$ 24.84 X
29	Rear LH door side rubber <i>lit</i>	1	\$ 49.22 ✓
30	Rear LH door inner board <i>could</i>	1	\$ 725.42 485 ✓
31	Rear LH door power window motor <i>3 NP</i>	1	\$ 453.79 X
32	Rear LH door power window regulator <i>3 NP</i>	1	\$ 453.79 X
33	Rear LH door inner lock <i>3 NP new</i>	1	\$ 245.75 X
34	Rear LH door sunrise visor	1	\$ 92.00 60(SV) ✓
35	Rear LH door frame black sticker <i>new</i>	1	\$ 34.61 ✓
36	Rear LH fender side garnish <i>lit</i>	1	\$ 176.18 ✓
37	Rear LH handle <i>lit</i>	1	\$ 77.16 ✓
38	Rear LH fender quarter garnish <i>lit</i>	1	\$ 55.77 ✓
39	LH door centre pillar <i>Dented</i>	1	\$ 1073.52 620 ✓
40	LH door centre pillar inner cover <i>abe new</i>	1	\$ 98.78 X

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : SLQ4401T
CHASSIS NO : RU11205272

MAKE / MODEL : HONDA VEZEL
ACCIDENT DATE : 27.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
41	LH rocker panel garnish <i>lt</i>	1	\$ 368.69 ✓
42	LH rocker panel <i>Repair</i>	1	\$ 437.69 X
43	Front LH sport rim <i>lt</i>	1	\$ 450.00 384.51
44	Front LH tyre <i>3 new</i>	1	\$ 437.00 X
45	Front LH knuckle arm <i>new</i>	1	\$ 420.78 X
46	Front LH knuckle arm bearing <i>and</i>	1	\$ 247.59 ✓
47	Front LH lower arm <i>Best</i>	1	\$ 403.53 ✓
48	Front windscreen <i>cracked</i>	1	\$ 2300.00 1380
49	Front windscreen rubber <i>new</i>	1	\$ 213.55 ✓
50	Front LH roof top side panel <i>Destroyed</i>	1	\$ 109.48 ✓
51	Front windscreen solar flim <i>new</i>	1	\$ 250.00 200.00
52	LH door glass solar flim @ \$200.00 <i>new</i>	2	\$ 400.00 200.00
53	Front LH door glass channel <i>3 new</i>	1	\$ 101.31 X
54	Rear LH door glass channel <i>new</i>	1	\$ 83.37 X
55	Rear LH door inner body rubber <i>new</i>	1	\$ 201.25 X
			\$ 19229.90
			\$ 3845.98
			\$ 15383.92

10810.36 S.N: 970
8648.28

LESS 20% DISC
TOTAL

LABOUR COST

1	To supply front windscreen sealant	1	\$ 50.00 ✓
2	Remove + refix front windscreen	1	\$ 200.00 120
3	Remove + refix door glass	1	\$ 200.00 120
4	Remove + refix upholstery	1	\$ 300.00 60
5	Remove + refix cushion	1	\$ 200.00 X
6	Remove + refix front LH suspension	1	\$ 400.00 150
7	Remove, replace + repair consistent to the accident	1	\$ 1800.00 1500
8	Respray painting	1	\$ 1500.00 120
9	Tuff kote	1	\$ 100.00 80
10	To check wheel alignment	1	\$ 100.00 80
TOTAL			\$ 4850.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAND TOTAL

\$ 20233.92

total: 12978.28

1/5: 10.3K

10.3K

Adrian King

1/5 29/08/24

10 Days