



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING SINGAPORE 068909

Ref: CS/UOI24080509/Uvp3

Date: 09/09/2024

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 3663S	Veh. Inspected	SLJ 2018S
Policy No.	-	Coverage	0
Claim No.	M11D00112409	Excess	\$0.00
Assign From	JOEL TAY	Assign Date	29/08/2024

2. Vehicle Details

Make & Model	HONDA CITY 1.5 SV CVT	C.C	1497
Engine No.	L15Z14112396	Year of Reg.	30/11/2016
Chassis No.	MRHGM6660HP000252	Colour	GREY
Odometer	156762 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/50R16	CHAMPIRO	6
L/H Front Tyre	195/50R16	CHAMPIRO	6
R/H Rear Tyre	195/50R16	WESTLAKE	6
L/H Rear Tyre	195/50R16	WESTLAKE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2024	Inspection Date	29/08/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days