

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

UNITED OVERSEAS INSURANCE LIMITED
146 ROBINSON ROAD, #02-01, UOI BUILDING
SINGAPORE 068909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES709600

Date : 28/08/2024

Vehicle Num. : SLJ 2018S

Make/Model : HONDA CITY

Chassis/Eng# :

Accident Date : 28/08/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER <i>DD</i>	<i>459.80</i>	663.70 ✓
2.	2PCS	REAR BUMPER SIDE RETAINER <i>N/S Bent 0/5 11</i>	<i>32.70</i>	65.40 ✓
3.	1PC	N/S REAR BUMPER REFLECTOR <i>11</i>		75.00 X
4.	1PC	N/S TAILLAMP <i>cnc</i>	<i>235.90</i>	535.90 ✓
5.	1PC	BOOT LID <i>DD Bent</i>	<i>554.10</i>	946.70 ✓
6.	1PC	BOOT LID LOCK <i>twl</i>	<i>148.50</i>	186.40 ✓
7.	1PC	BOOT LID WEATHERSTRIP <i>twl</i>	<i>120.80</i>	150.20 ✓
8.	1PC	BOOT LID LOGO EMBLEM <i>neu</i>	<i>33.20</i>	44.70 ✓
9.	1PC	BOOT LID CITY EMBLEM <i>neu</i>	<i>32.00</i>	42.50 ✓
10.	1PC	BOOT LID I-VTEC EMBLEM <i>neu</i>	<i>35.00</i>	43.50 ✓
11.	1PC	BOOT LID CHROME GARNISH <i>AA</i>		228.30 X
12.	1PC	N/S BOOT LAMP <i>cnc</i>	<i>120.90</i>	338.90 ✓
13.	1PC	REAR END PANEL <i>DD Bent</i>	<i>403.70</i>	585.20 ✓
14.	1PC	REAR END PANEL GARNISH <i>twl</i>	<i>66.60</i>	128.60 ✓
15.	1PC	SPARE TYRE BOARD <i>twl</i>	<i>122.80</i>	389.00 ✓
16.	1PC	N/S REAR FENDER INNER SHIELD <i>11</i>		92.00 X
List Total S\$:				4,516.00
20.00% Discount S\$:				903.20
				3,612.80
SPECIAL NETT ITEMS :				
1.	1SET	REAR BUMPER CLIP <i>neu</i>		50.00 <i>30</i>

CONTINUE / ...

not allowed
neu
moras
90496608
29/8/24
1/c #3300
6 days
Whisper the up

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

UNITED OVERSEAS INSURANCE LIMITED
146 ROBINSON ROAD, #02-01, UOI BUILDING
SINGAPORE 068909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES709600

Date : 28/08/2024
Vehicle Num. : SLJ 2018S
Make/Model : HONDA CITY
Chassis/Eng# :
Accident Date : 28/08/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1PC	BOOT LID SEALANT ¹¹		80.00 X
3.	1PC	BOOT LID INSULATOR CLIP ¹¹		50.00 X
4.	1SET	REAR FENDER INNER TRIM CLIP ¹¹		50.00 X
5.	1SET	REVERSE CAMERA ^{1A}		480.00 X
6.	1SET	REVERSE SENSOR ^{8u}		250.00 X
7.	1SET	N/S REAR FENDER INNER SHIELD CLIPS ¹¹		50.00 X
8.	1PC	REAR NUMBER PLATE ¹¹		50.00 X
Special Nett Total S\$:				1,060.00
LABOUR :				
TO CHECK LIGHT AND WIRING				50.00 ²⁰
TRANSFER BOOT LID PARTS				100.00 ⁵⁰
INSTALL REVERSE SENSOR				80.00 ³⁰
INSTALL REVERSE CAMERA				150.00 X
ANTI-RUST				120.00 ⁵⁰
TO APPLY BODY SEALANT ON BODY JOINTS				120.00 X
TO REMOVE/REFIT INNER TRIMS AND GARNISHES				120.00 ⁶⁰
LABOUR/PANEL BEATING- REPAIR FENDER AND SPARE TYRE PANEL				1,100.00 ¹⁰⁰⁰
SPRAY PAINTING				1,200.00 ¹⁰⁵⁰
Labour Total S\$:				3,040.00

E. & O.E.

Total S\$: 7,712.80

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2,235.30
202
1884.24
30
2260
4174.24
202
3339.