

ASS. REC. BY:

REF: C12 / CS/CTI24080513/Kvh3

C

*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Oping

of 216C

Insured: PC 2115J

Policy No. \_\_\_\_\_

Claims No. SNM24D204853

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 887K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLF 85184 Yr Regn: 07 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Volkswagen Passat c.c. 1798

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 105165 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVW 888 3C 8K E 09 2292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 0 mm R/Bal. 0 mm

L/Bal. 0 mm L/Bal. 0 mm

D.O.A. 28/8/24 D.O.I. 2/9/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body & u/c

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/10/24 11:30 @ 20,900: 20,900 Comb (red 23,238.20, 52%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

Days Of Repair: 9

Resurvey No. of Trlp: \_\_\_\_\_

Survey Fee:

Transportation

S + RS. SI

Fuel

Others

TOTAL

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	216C
Vehicle Details	
Vehicle No.:	SLF8518Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Aug 2024
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT B8 1.8 TFSI AT 3G24JZ
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	CJS299272
Chassis No.:	WVWZZZ3CZKE092292
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$28,714.00
Original Registration Date:	25 Jul 2019
First Registration Date:	25 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$32,200.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2029
PARF Rebate Amount:	\$22,540.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jul 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,406.00
COE Rebate Amount:	\$19,300.00
<b>Total Rebate Amount:</b>	<b>\$41,840.00</b>
Message	

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 31 Aug 2024

OK

Date: 30/08/2024  
 Vehicle No: SLF8518Y  
 Model: VOLKSWAGEN PASSAT 1.8  
 Chassis: WVWZZZ3CKZKE092292-2019  
 Reg.Year: 2019

*NOT AUTHORIZED*  
*L/R Rep &*  
*Recovery After Pain*  
*9 days*

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: PC2115J  
 Date of Accident: 29/08/2024  
 Estimator: TING AN  
 Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		R \$1,550.00	X
2	FRONT BONNET HINGE LH	1		R \$75.00	X
3	FRONT HEADLAMP LH	1		R \$3,200.00	X
4	FRONT FENDER LH	1		R \$928.00	✓
5	FRONT FENDER UPPER CHROME MOULDING LH	1		R \$119.00	✓
6	FRONT FENDER LOWER COVER LH	1		\$104.00	?
7	FRONT FENDER LOWER CHROME MOULDING LH	1		\$119.00	?
8	FRONT FENDER INNER SHIELD LH	1		R \$265.00	X
9	FRONT SIDE MIRROR ASSEMBLY LH	1		R \$785.00	✓
10	FRONT SIDE MIRROR COVER LH	1		mi \$195.00	✓
11	FRONT ABSORBER LH	1		\$494.00	?
12	FRONT LOWER ARM LH	1		\$621.00	?
13	FRONT KNUCKLE ARM LH	1		\$954.00	?
14	FRONT WHEEL BEARING LH	1		\$751.00	?
15	FRONT DRIVESHAFT LH	1		R \$2,134.00	X
16	FRONT TIE ROD LH	1		\$262.00	?
17	FRONT TIE ROD END LH	1		\$176.00	?
18	FRONT DOOR LH	1		R \$3,668.00	✓
19	FRONT DOOR WEATHERSTRIP LH	1		R \$379.00	50% ✓
20	FRONT DOOR INNER TRIM BOARD LH	1		\$1,817.00	?
21	FRONT DOOR WINDOW REGULATOR LH	1		\$592.00	?
22	FRONT DOOR WINDOW MOTOR LH	1		\$522.00	?
23	FRONT DOOR UPPER CHROME MOULDING LH	1		R \$288.00	X
24	FRONT DOOR LOWER CHROME MOULDING LH	1		R \$228.00	✓
25	FRONT DOOR LOWER PROTECTOR LH	1		\$179.00	?
26	FRONT DOOR HANDLE LH	1		R \$580.00	X
27	FRONT DOOR LOCK	1		R \$605.00	X
28	FRONT DOOR UPPER HINGE LH	1		R \$55.00	X
29	FRONT DOOR LOWER HINGE LH	1		R \$55.00	X
30	FRONT DOOR CHECKER LH	1		\$159.00	?
31	REAR DOOR LH	1		R \$3,668.00	✓
32	REAR DOOR WEATHERSTRIP LH	1		R \$379.00	50% ✓
33	REAR DOOR INNER TRIM BOARD LH	1		R \$1,812.00	X
34	REAR DOOR WINDOW REGULATOR LH	1		\$572.00	?
35	REAR DOOR WINDOW MOTOR LH	1		\$501.00	?
36	REAR DOOR HANDLE LH	1		R \$520.00	X

**Head office**

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/08/2024  
 Vehicle No: SLF8518Y  
 Model: VOLKSWAGEN PASSAT 1.8  
 Chassis: WVVZZZ3CKZKE092292-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: PC2115J  
 Date of Accident: 29/08/2024  
 Estimator: TING AN  
 Surveyor:

37	REAR DOOR LOCK LH	1		<i>RM</i> \$798.00	X
38	REAR DOOR LOWER CHROME LH	1		<i>RM</i> \$202.00	—
39	REAR DOOR LOWER PROTECTOR LH	1		\$179.00	?
40	SIDE SKIRT LH	1		\$620.00	?
41	REAR FENDER LH	1		<i>RM</i> \$3,476.00	✓
42	REAR FENDER INNER SHIELD LH	1		<i>RM</i> \$283.00	X
43	REAR FENDER LOWER CHROME MOULDING LH	1		<i>RM</i> \$150.00	✓
44	REAR WINDSCREEN MOULDING	1		<i>RM</i> \$130.00	✓
45	REAR ABSORBER LH	1		\$499.00	?
46	REAR KNUCKLE ARM LH	1		\$955.00	?
47	REAR WHEEL BEARING LH	1		\$751.00	?
48	REAR LOWER ARM LH	1		\$730.00	?
49	REAR BUMPER	1	<i>msm</i>	<i>RM</i> \$2,009.00	✓
50	REAR BUMPER SIDE BRACKET LH	1		<i>RM</i> \$132.00	X
51	REAR BUMPER CHROME MOULDING LH	1		<i>RM</i> \$273.00	X
52	FRONT BUMPER	1		REPAIR	
				SUB TOTAL	\$40,498.00
				LESS 10%	-\$4,049.80
				PARTS TOTAL	\$36,448.20

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1		<i>RM</i> \$50.00	—
2	REAR DOOR INNER TRIM BOARD CLIPS LH	1		<i>RM</i> \$50.00	—
3	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>RM</i> \$40.00	—
4	FRONT RIM LH	1		<i>RM</i> \$500.00	—
5	REAR RIM LH	1		<i>RM</i> \$500.00	—
6	REAR WINDSCREEN SEALANT	1		<i>RM</i> \$100.00	✓
7	REAR FENDER INNER SHIELD CLIPS LH	1		<i>RM</i> \$40.00	X
8	REAR BUMPER CLIPS	1		<i>RM</i> \$50.00	✓
				S/N TOTAL	\$1,330.00

Date: 30/08/2024  
 Vehicle No: SLF8518Y  
 Model: VOLKSWAGEN PASSAT 1.8  
 Chassis: WVWZZZ3CKZKE092292-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: PC2115J  
 Date of Accident: 29/08/2024  
 Estimator: TING AN  
 Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	\$2,500.00	<i>1300</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH, SIDE SKIRT LH, REAR BUMPER & ETC.	\$2,000.00	<i>1350</i>
LABOUR CHARGES TO REMOVE & REINSTALL FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.	\$150.00	<i>120</i>
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.	\$400.00	<i>100</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR UNDERCARRIAGE PARTS.	\$500.00	<i>7</i>
TO WHEEL ALIGNMENT & BALANCING.	\$120.00	<i>40</i>
TO DAIGNOSIS FAULT CODE & ETC.	\$300.00	<i>7</i>
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00	<i>30</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$6,360.00

TING AN

**TOTAL \$44,138.20**

Acknowledged by Repairer  
 Signature:  
 Date:

Date: 30/08/2024

Vehicle No: SLF8518Y

Model: VOLKSWAGEN PASSAT 1.8

Chassis: WVVZZZ3CKZKE092292-2019

Reg.Year: 2019

*Not Authorized*

*L1 Pmp & 29800/pc*

*20,900*

*Recovery After Pains 9 days*

Third Party Insurer: CHINA TAIPING

Third Party Veh No: PC2115J

Date of Accident: 29/08/2024

Estimator: TING AN

Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		R \$1,550.00	X
2	FRONT BONNET HINGE LH	1		R \$75.00	X
3	FRONT HEADLAMP LH	1		R \$3,200.00	X
4	FRONT FENDER LH <i>725.90</i>	1		R \$928.00	✓
5	FRONT FENDER UPPER CHROME MOULDING LH	1		R \$119.00	✓
6	FRONT FENDER LOWER COVER LH	1		R \$104.00	2
7	FRONT FENDER LOWER CHROME MOULDING LH	1		R \$119.00	2
8	FRONT FENDER INNER SHIELD LH	1		R \$265.00	X
9	FRONT SIDE MIRROR ASSEMBLY LH	1		R \$785.00	✓
10	FRONT SIDE MIRROR COVER LH	1		R \$195.00	✓
11	FRONT ABSORBER LH	1		R \$494.00	2
12	FRONT LOWER ARM LH <i>495</i>	1		R \$621.00	2
13	FRONT KNUCKLE ARM LH <i>667.50</i>	1		R \$954.00	2
14	FRONT WHEEL BEARING LH <i>411.90</i>	1		R \$751.00	2
15	FRONT DRIVESHAFT LH	1		R \$2,134.00	X
16	FRONT TIE ROD LH	1		R \$262.00	2
17	FRONT TIE ROD END LH	1		R \$176.00	2
18	FRONT DOOR LH <i>2980</i>	1		R \$3,668.00	✓
19	FRONT DOOR WEATHERSTRIP LH	1	<i>189.501N</i>	R \$379.00	501N
20	FRONT DOOR INNER TRIM BOARD LH <i>1085</i>	1	<i>mg cm</i>	R \$1,817.00	2
21	FRONT DOOR WINDOW REGULATOR LH <i>504</i>	1		R \$592.00	2
22	FRONT DOOR WINDOW MOTOR LH	1		R \$522.00	2
23	FRONT DOOR UPPER CHROME MOULDING LH	1		R \$288.00	X
24	FRONT DOOR LOWER CHROME MOULDING LH	1		R \$228.00	✓
25	FRONT DOOR LOWER PROTECTOR LH	1		R \$179.00	2
26	FRONT DOOR HANDLE LH	1		R \$580.00	X
27	FRONT DOOR LOCK	1		R \$605.00	X
28	FRONT DOOR UPPER HINGE LH	1		R \$55.00	X
29	FRONT DOOR LOWER HINGE LH	1		R \$55.00	X
30	FRONT DOOR CHECKER LH	1		R \$159.00	X
31	REAR DOOR LH <i>2890</i>	1		R \$3,668.00	✓
32	REAR DOOR WEATHERSTRIP LH	1	<i>189.501N</i>	R \$379.00	501N
33	REAR DOOR INNER TRIM BOARD LH <i>1480</i>	1		R \$1,812.00	X
34	REAR DOOR WINDOW REGULATOR LH	1		R \$572.00	2
35	REAR DOOR WINDOW MOTOR LH	1		R \$501.00	2
36	REAR DOOR HANDLE LH	1		R \$520.00	X

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1943

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 30/08/2024  
 Vehicle No: SLF8518Y  
 Model: VOLKSWAGEN PASSAT 1.8  
 Chassis: WVVZZZ3CKZKE092292-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: PC2115J  
 Date of Accident: 29/08/2024  
 Estimator: TING AN  
 Surveyor:

NO.	DESCRIPTION	QTY	UNIT	AMOUNT	MARKS
37	REAR DOOR LOCK LH <i>618</i>	1	<i>Ref</i>	\$798.00	<i>✓</i>
38	REAR DOOR LOWER CHROME LH	1	<i>Ref</i>	\$202.00	<i>✓</i>
39	REAR DOOR LOWER PROTECTOR LH	1	<i>Ref</i>	\$179.00	<i>✓</i>
40	SIDE SKIRT LH	1	<i>my car</i>	\$620.00	<i>✓</i>
41	REAR FENDER LH <i>2316</i>	1	<i>Ref</i>	\$3,476.00	<i>✓</i>
42	REAR FENDER INNER SHIELD LH	1	<i>Ref</i>	\$283.00	<i>X</i>
43	REAR FENDER LOWER CHROME MOULDING LH	1	<i>Ref</i>	\$150.00	<i>✓</i>
44	REAR WINDSCREEN MOULDING	1	<i>Ref</i>	\$130.00	<i>✓</i>
45	REAR ABSORBER LH	1	<i>Ref</i>	\$499.00	<i>✓</i>
46	REAR KNUCKLE ARM LH <i>796.20</i>	1	<i>Ref</i>	\$955.00	<i>✓</i>
47	REAR WHEEL BEARING LH <i>381</i>	1	<i>Ref</i>	\$751.00	<i>✓</i>
48	REAR LOWER ARM LH <i>697.40</i>	1	<i>Ref</i>	\$730.00	<i>✓</i>
49	REAR BUMPER <i>1537.20</i>	1	<i>my car</i>	\$2,009.00	<i>✓</i>
50	REAR BUMPER SIDE BRACKET LH	1	<i>Ref</i>	\$132.00	<i>X</i>
51	REAR BUMPER CHROME MOULDING LH	1	<i>Ref</i>	\$273.00	<i>X</i>
52	FRONT BUMPER	1		REPAIR	
SUB TOTAL				\$40,498.00	
LESS 10%				-\$4,049.80	
PARTS TOTAL				\$36,448.20	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	MARKS
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1		<i>Ref</i> \$50.00	<i>✓</i>
2	REAR DOOR INNER TRIM BOARD CLIPS LH	1		<i>Ref</i> \$50.00	<i>✓</i>
3	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>Ref</i> \$40.00	<i>✓</i>
4	FRONT RIM LH	1		<i>Ref</i> \$500.00	<i>✓</i>
5	REAR RIM LH	1		<i>Ref</i> \$500.00	<i>✓</i>
6	REAR WINDSCREEN SEALANT	1		<i>Ref</i> \$100.00	<i>✓</i>
7	REAR FENDER INNER SHIELD CLIPS LH	1		<i>Ref</i> \$40.00	<i>X</i>
8	REAR BUMPER CLIPS	1		<i>Ref</i> \$50.00	<i>✓</i>
S/N TOTAL				\$1,330.00	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Head office**

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 6 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6487 1863

**Branch (Motor Insurance Claims)**

BIK 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Signature:  
 Date:

Date: 30/08/2024  
 Vehicle No: SLF8518Y  
 Model: VOLKSWAGEN PASSAT 1.8  
 Chassis: WVVZZZ3CKZKE092292-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: PC2115J  
 Date of Accident: 29/08/2024  
 Estimator: TING AN  
 Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	\$2,500.00	<i>1300</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH, SIDE SKIRT LH, REAR BUMPER & ETC.	\$2,000.00	<i>1350</i>
LABOUR CHARGES TO REMOVE & REINSTALL FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>60</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.	\$150.00	<i>120</i>
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.	\$400.00	<i>100</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR UNDERCARRIAGE PARTS.	\$500.00	<i>380</i>
TO WHEEL ALIGNMENT & BALANCING.	\$120.00	<i>80</i>
TO DAIGNOSIS FAULT CODE & ETC.	\$300.00	<i>70</i>
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00	<i>30</i>

**LABOUR TOTAL** \$6,360.00

TING AN **TOTAL** \$44,138.20

**Head office**

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

