

Date: 30/08/2024
 Vehicle No: SLF8518Y
 Model: VOLKSWAGEN PASSAT 1.8
 Chassis: WVVZZZ3CKZKE092292-2019
 Reg. Year: 2019

NOT Authorized
L1 Rep & 29800/1
20,900/1
Recovery After Paint
9 days

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: PC2115J
 Date of Accident: 29/08/2024
 Estimator: TING AN
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET	1		R \$1,550.00	X
2	FRONT BONNET HINGE LH	1		R \$75.00	X
3	FRONT HEADLAMP LH	1		R \$3,200.00	X
4	FRONT FENDER LH <i>725.90</i>	1		R \$928.00	✓
5	FRONT FENDER UPPER CHROME MOULDING LH	1		R \$119.00	✓
6	FRONT FENDER LOWER COVER LH	1		R \$104.00	2
7	FRONT FENDER LOWER CHROME MOULDING LH	1		R \$119.00	2
8	FRONT FENDER INNER SHIELD LH	1		R \$265.00	X
9	FRONT SIDE MIRROR ASSEMBLY LH	1		R \$785.00	✓
10	FRONT SIDE MIRROR COVER LH	1		R \$195.00	✓
11	FRONT ABSORBER LH	1		R \$494.00	2
12	FRONT LOWER ARM LH <i>495</i>	1		R \$621.00	2
13	FRONT KNUCKLE ARM LH <i>667.50</i>	1		R \$954.00	2
14	FRONT WHEEL BEARING LH <i>411.30</i>	1		R \$751.00	2
15	FRONT DRIVESHAFT LH	1		R \$2,134.00	X
16	FRONT TIE ROD LH	1		R \$262.00	2
17	FRONT TIE ROD END LH	1		R \$176.00	2
18	FRONT DOOR LH <i>2980</i>	1		R \$3,668.00	✓
19	FRONT DOOR WEATHERSTRIP LH	1	<i>189.50/1</i>	R \$379.00	50/1
20	FRONT DOOR INNER TRIM BOARD LH <i>1085</i>	1		R \$1,817.00	2
21	FRONT DOOR WINDOW REGULATOR LH <i>504</i>	1		R \$592.00	2
22	FRONT DOOR WINDOW MOTOR LH	1		R \$522.00	2
23	FRONT DOOR UPPER CHROME MOULDING LH	1		R \$288.00	X
24	FRONT DOOR LOWER CHROME MOULDING LH	1		R \$228.00	✓
25	FRONT DOOR LOWER PROTECTOR LH	1		R \$179.00	2
26	FRONT DOOR HANDLE LH	1		R \$580.00	X
27	FRONT DOOR LOCK	1		R \$605.00	X
28	FRONT DOOR UPPER HINGE LH	1		R \$55.00	X
29	FRONT DOOR LOWER HINGE LH	1		R \$55.00	X
30	FRONT DOOR CHECKER LH	1		R \$159.00	2
31	REAR DOOR LH <i>2890</i>	1		R \$3,668.00	✓
32	REAR DOOR WEATHERSTRIP LH	1	<i>189.50/1</i>	R \$379.00	50/1
33	REAR DOOR INNER TRIM BOARD LH <i>1480</i>	1		R \$1,812.00	X
34	REAR DOOR WINDOW REGULATOR LH	1		R \$572.00	2
35	REAR DOOR WINDOW MOTOR LH	1		R \$501.00	2
36	REAR DOOR HANDLE LH	1		R \$520.00	X

Date: 30/08/2024
 Vehicle No: SLF8518Y
 Model: VOLKSWAGEN PASSAT 1.8
 Chassis: WVWZZZ3CKZKE092292-2019
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: PC2115J
 Date of Accident: 29/08/2024
 Estimator: TING AN
 Surveyor:

37	REAR DOOR LOCK LH <i>618</i>	1	<i>Ref R</i>	\$798.00	<i>* ✓</i>
38	REAR DOOR LOWER CHROME LH	1	<i>na</i>	\$202.00	<i>—</i>
39	REAR DOOR LOWER PROTECTOR LH	1	<i>na</i>	\$179.00	<i>✓</i>
40	SIDE SKIRT LH	1	<i>my int</i>	\$620.00	<i>✓</i>
41	REAR FENDER LH <i>2316</i>	1	<i>R1</i>	\$3,476.00	<i>✓</i>
42	REAR FENDER INNER SHIELD LH	1	<i>na</i>	\$283.00	<i>X</i>
43	REAR FENDER LOWER CHROME MOULDING LH	1	<i>na</i>	\$150.00	<i>—</i>
44	REAR WINDSCREEN MOULDING	1	<i>na</i>	\$130.00	<i>—</i>
45	REAR ABSORBER LH	1	<i>R1</i>	\$499.00	<i>✓</i>
46	REAR KNUCKLE ARM LH <i>796.20</i>	1	<i>R1</i>	\$955.00	<i>✓</i>
47	REAR WHEEL BEARING LH <i>381</i>	1	<i>na</i>	\$751.00	<i>✓</i>
48	REAR LOWER ARM LH <i>697.40</i>	1	<i>DIS</i>	\$730.00	<i>✓</i>
49	REAR BUMPER <i>1537.20</i>	1	<i>my int</i>	\$2,009.00	<i>—</i>
50	REAR BUMPER SIDE BRACKET LH	1	<i>R1</i>	\$132.00	<i>X</i>
51	REAR BUMPER CHROME MOULDING LH	1	<i>na</i>	\$273.00	<i>X</i>
52	FRONT BUMPER	1		REPAIR	
				SUB TOTAL	\$40,498.00
				LESS 10%	-\$4,049.80
				PARTS TOTAL	\$36,448.20

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1		<i>na</i> \$50.00	<i>—</i>
2	REAR DOOR INNER TRIM BOARD CLIPS LH	1		<i>na</i> \$50.00	<i>—</i>
3	FRONT FENDER INNER SHIELD CLIPS LH	1		<i>na</i> \$40.00	<i>—</i>
4	FRONT RIM LH	1		<i>Ref</i> \$500.00	<i>—</i>
5	REAR RIM LH	1		<i>Ref</i> \$500.00	<i>—</i>
6	REAR WINDSCREEN SEALANT	1		<i>na</i> \$100.00	<i>405n</i>
7	REAR FENDER INNER SHIELD CLIPS LH	1		<i>na</i> \$40.00	<i>X</i>
8	REAR BUMPER CLIPS	1		<i>na</i> \$50.00	<i>✓</i>
				S/N TOTAL	\$1,330.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office
5 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1955

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind, Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Signature:
Date:

Date: 30/08/2024
Vehicle No: SLF8518Y
Model: VOLKSWAGEN PASSAT 1.8
Chassis: WVVZZZ3CKZKE092292-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: PC2115J
Date of Accident: 29/08/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.	\$2,500.00	<i>130d</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH, SIDE SKIRT LH, REAR BUMPER & ETC.	\$2,000.00	<i>135d</i>
LABOUR CHARGES TO REMOVE & REINSTALL FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>6d</i>
LABOUR CHARGES TO REMOVE & REINSTALL REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	<i>6d</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.	\$150.00	<i>12d</i>
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.	\$400.00	<i>10d</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR UNDERCARRIAGE PARTS.	\$500.00	<i>38d</i>
TO WHEEL ALIGNMENT & BALANCING.	\$120.00	<i>4d</i>
TO DAIGNOSIS FAULT CODE & ETC.	\$300.00	<i>7d</i>
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00	<i>3d</i>

LABOUR TOTAL \$6,360.00

TING AN **TOTAL** \$44,138.20

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

