



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLR 9028A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LEFT DOOR	TO REPAIR SEE LABOUR	\$1,688.00	\$0.00
1	REAR LEFT DOOR	DENTED	\$2,121.00	\$1,408.00
1	LEFT SIDE SKIRT	TO REPAIR SEE LABOUR	\$866.00	\$0.00
1	LEFT REAR FENDER	TO REPAIR SEE LABOUR	\$859.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,106.80)	(\$281.60)
			\$4,427.20	\$1,126.40

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO FIX & DISMANTLE AND REMOVE DAMAGED LEFT PORTIONS; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF FRONT LEFT DOOR, LEFT SIDE SKIRT AND LEFT REAR FENDER }		\$800.00	\$400.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS }		\$0.00	\$0.00
	TO CHECK WIRING }		\$0.00	\$0.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT }		\$0.00	\$0.00
	SPRAY PAINTING FOR REAR PORTIONS AFFECTED PARTS		\$1,000.00	\$800.00
	PROGRAMMING FOR HYBRID SYSTEM RESET (NPA)	NOT NECESSARY	\$0.00	\$0.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE (NPA)	NOT NECESSARY	\$0.00	\$0.00
	3D WHEEL ALIGNMENT (NPA)	NOT NECESSARY	\$0.00	\$0.00
	TO APPLY WATERPROOFING SEALER ON END AND FRONT SUPPORT PANELS (NPA)	NOT NECESSARY	\$0.00	\$0.00
			\$1,800.00	\$1,200.00

GRAND TOTAL	\$6,227.20	\$2,326.40
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,800.00
---	--	-------------------

Report Ref No: CS/SMO24080514/Uvp3m4

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.