

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANC	CE SINGAPORE PL	Ref:	CS/SMO24080514/Uvp3m4	
	50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Date:	12/09/2024	
	SINGAPORE LAND	TOWER SINGAPORE 048623	Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGB 47Y	Veh. Inspected	SLR 9028A	
	Policy No.	D24MTPV01001587	Coverage	0	
	Claim No.	CMTD2402793/AGC	Excess	\$0.00	
	Assign From	GRACE TEO	Assign Date	29/08/2024	
2.	Vehicle Details				
	Make & Model	HONDA FREED 1.5G HYBRID AUTO	C.C	1496	
	Engine No.	LEB5528910	Year of Reg.	30/08/2017	
	Chassis No.	GB71007603	Colour	BLUE	
	Odometer	231973 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/65R15	DUNLOP	6	
	L/H Front Tyre	185/65R15	DUNLOP	6	
	R/H Rear Tyre	185/65R15	DUNLOP	6	
	L/H Rear Tyre	185/65R15	DUNLOP	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	24/08/2024	Inspection Date	03/09/2024	
	Survey held at	JSSM AUTOSOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-13, PR	EMIER @ KAKI BU	KIT SINGAPORE 415875	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Day	s of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days