

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SLR9028A
Chassis No. : GB71007603
Engine No. : LEB5528910
Date of Accident : 24.08.2024

Reference No. : 240824-TPC-JSSM07
Make/Model : HONDA / FREED
Date : 03.09.2024

Replacement of Damaged Parts

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's Estimates</u>
1	1	Front Left Door	Dented	\$ 1,688.00
2	1	Rear Left Door	Scratches	\$ 2,121.00
3	1	Left Side Skirt	Scratches	\$ 866.00
4	1	Left Rear Fender	Scratches	\$ 859.00
				\$ 5,534.00

Total (Parts): \$ 5,534.00
-20% \$ 4,427.20

Labour Charges

5	To fix & dismantle and remove damaged Left Portions; affected damaged portion.	\$ 800.00
6	To apply anti rust coat and affected areas	\$ -
7	To check wiring	\$ -
8	Welding and cutting of affected panels, including chassis alignment.	\$ -
9	Spray painting for Rear Portions affected parts	\$ 1,000.00
10	Programming for Hybrid System Reset	\$ -
11	Diagnose ECU system and reset error code.	\$ -
12	3D Wheel Alignment	\$ -
13	To Apply Waterproofing sealer on End and Front Support Panels	\$ -
Total Labour:		\$ 1,800.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 6,227.20

Less 20% \$ 4,981.76

JSSM AUTOSOLUTIONS PTE LTD

Page 1

not Adjusted
any
3 days
3/9/24
whenever Henry
HP. 90096608
L/S \$ 1800

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-1408
202
1126.40
1200
2326.40
202
1801.