



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 ON BEHALF OF GOH TONG CHUAN		Ref: Date: Code:	CS/TP24080516/Unp3e2 12/09/2024 TP149
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGX 2860L	Veh. Inspected	SJL 3344G
	Policy No.	-	Coverage	0
	Claim No.	-	Excess	\$0.00
	Assign From	-	Assign Date	29/08/2024
2. Vehicle Details				
	Make & Model	M.G. HS 1.5T (A)	C.C	1490
	Engine No.	15E4E8AGL8210072	Year of Reg.	29/09/2020
	Chassis No.	LSJA24U93LN029190	Colour	BLUE
	Odometer	35984 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	235/50R18	BRIDGESTONE	7
	L/H Front Tyre	235/50R18	BRIDGESTONE	7
	R/H Rear Tyre	235/50R18	BRIDGESTONE	7
	L/H Rear Tyre	235/50R18	BRIDGESTONE	7
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	23/08/2024	Inspection Date	29/08/2024
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL - BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				