



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 ON BEHALF OF GOH TONG CHUAN		Ref: CS/TP24080516/Unp3e2 Date: 12/09/2024 Code: TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SJL 3344G	
	Policy No. -	Coverage	0	
	Claim No. -	Excess	\$0.00	
	Assign From -	Assign Date	29/08/2024	
2. Vehicle Details				
	Make & Model	M.G. HS 1.5T (A)	C.C	1490
	Engine No.	15E4E8AGL8210072	Year of Reg.	29/09/2020
	Chassis No.	LSJA24U93LN029190	Colour	BLUE
	Odometer	35984 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	235/50R18	BRIDGESTONE	7
	L/H Front Tyre	235/50R18	BRIDGESTONE	7
	R/H Rear Tyre	235/50R18	BRIDGESTONE	7
	L/H Rear Tyre	235/50R18	BRIDGESTONE	7
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	23/08/2024	Inspection Date	29/08/2024
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL - BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				