

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Allowed
his
moda
29/8/24 Repair Sun 4500
5 days.

VEHICLE No: SJL 3344G

NETT ITEM

1PC	REAR WINDSCREEN MOULDING	11	\$145.40 X
1PC	TAILGATE	R	\$2,700.00 X
2PCS	TAILGATE REFLECTORS @\$537.00	11	\$1,074.00 X
1PC	TAILGATE INNER LOCK	11	\$516.80 X
1PC	TAILGATE REAR LOGO	su	\$115.00 X
1PC	TAILGATE WEATHERSTRIP	11	\$366.20 X
1PC	TAILGATE INNER TRIM BOARD	11	\$467.30 X
1PC	REAR BUMPER UPPER	2e / torn	\$974.00 —
1PC	REAR BUMPER CENTER BLACK	De	\$573.00 —
1PC	REAR BUMPER LOWER SILVER	torn	\$574.00 —
1PC	REAR BUMPER SIDE RETAINERS @\$65.00	11	\$130.00 X
1PC	REAR BUMPER BEAM	11	\$596.00 —
1PC	REAR BUMPER LAMP N/S	one	\$285.00 —
2PCS	REAR BUMPER PDC SENSORS @\$165.00	molded	\$330.00 12 C
4PCS	REAR BUMPER PDC SENSOR BRACKETS @\$28.00	11	\$112.00 —
1PC	REAR PDC SENSOR WIRE		\$292.00
1PC	REAR END PANEL OUTER	R	\$401.00 X
1PC	REAR END PANEL INNER	R	\$580.00 X
1PC	REAR END PANEL TOP GARNISH	11	\$381.80 X
1PC	TAILLAMP N/S	11	\$947.00 X
1PC	REAR FENDER OUTER PROTECTOR N/S	2e / torn	\$245.20 —
1PC	REAR EXHAUST	R	\$4,500.00 X
1PC	REAR EXHAUST CHROME N/S	su	\$180.00 X
			\$16,485.70
		LESS 10%	\$14,837.13

S.NETT

1PC	REAR LICENCE PLATE	11	\$50.00 X
1PC	REAR WINDSCREEN SEALANT	11	\$50.00 X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00 X
1SET	REAR BUMPER CLIPS	11	\$50.00 ✓
	TO CHECK WIRING		\$50.00 20
	TO REMOVE & REPLACED REAR REVERSE SENSOR		\$80.00 50
	TO REMOVE & REFIX REAR WINDSCREEN	11	\$150.00 X
	TO REMOVE & REFIX TAILGATE MECHANISM	11	\$100.00 X
	TO REMOVE & REFIX CUSHION UPHOLSTERY		\$120.00 50
	TO REMOVE & REFIX REAR EXHAUST		\$100.00 60
	TO REMOVE & REFIX FUEL TANK	11	\$100.00 X
	TO REMOVE & REFIX REAR REVERSE CAMERA	11	\$100.00 X

TO SPRAY ANTI-RUST PROOFING
 TO DIAGNOSIS & REPROGRAMME SYSTEM
 LABOUR FOR PANEL BEATING
 TO PUTTY & SPRAY PAINTING

17 \$120.00 X
 \$180.00 120
 \$1,800.00 700
 \$1,800.00 800
 TOTAL \$19,737.13

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-35242
 102
 3171.78
 50
 1800
 5071.78
 102
 4519