

ASS. REC. BY:

REF: LIP/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8122k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: YR 1906PYr Regn: 03.24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mit CarterC.C. 2998Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 20678

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21EA 36281Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 195/85R15(0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 9 mmL/Bal. 9 mmL/Bal. 9 9 mmD.O.A. 13/8/24D.O.I. 30/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CLSM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation

S - RS. SI

Fees

Others

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 29/08/24
VEHICLE : YR1906P
MAKE/MODEL : MITSUBISHI CANTER
CHASSIS NO : FEB21EA36261
MILLAGE :
TYRE SIZE : 195/85 R15
DOA : 13/08/24
TP INSURANCE : LIBERTY

Not Authorized
1/19/8
Painting After Rain
2 days

List items

01 PC	RH DOOR	\$ 1,910.15	✓
01 PC	RH DOOR INNER LOCK	\$ 466.29	X
01 PC	RH DOOR CATCH LOCK	\$ 65.30	X
02 PC	RH DOOR HINGES @ \$145.90	\$ 291.80	X
01 PC	RH DOOR CHECKER	\$ 220.80	X
01 PC	RH DOOR WEATERSTRIP	\$ 250.60	X
01 PC	RH DOOR UNDER RUBBER	\$ 85.60	X
01 PC	RH DOOR GLASS RAILWAY	\$ 154.30	X
01 PC	RH DOOR FRAME INNER RUBBER	\$ 364.50	X
01 PC	RH POWER WINDOW REGULATOR	\$ 365.40	?
01 PC	RH POWER WINDOW MOTOR	\$ 755.43	?
01 PC	RH DOOR SPEAKER	\$ 361.55	X
01 PC	RH DOOR OUTER HANDLE	\$ 256.30	✓
01 PC	RH DOOR OUTER MOULDING	\$ 264.50	✓
01 PC	RH DOOR WHEEL ARCH	\$ 286.40	✓
01 PC	RH DOOR INNER TRIM BOARD	\$ 756.20	X
01 PC	RH DOOR STICKER 'BLUETEC'	\$ 85.60	—
01 PC	RH DOOR STICKER 'DUONIC'	\$ 82.30	—
01 PC	RH STEP PANEL	\$ 365.20	X
01 PC	RH HEAD LAMP	\$ 453.60	X
01 PC	RH HEAD LAMP UNDER COVER	\$ 212.30	X
		\$ 8,054.12	

TOTAL PARTS COST

Special Nett Item:

10 PC DOOR TRIM BOARD CLIP @ \$8.00

\$ 80.00 X
\$ 80.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
4. TO SUPPLY COMPUTER DIANOGTIC

\$ 500.00 2001
\$ 300.00 2002
\$ 100.00 201
\$ 100.00 X
\$ 1,000.00

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 8,054.12
\$ 80.00
\$ 1,000.00
\$ 9,134.12