

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

bee tr
OERR
TP Chin.
Xiao Chin.

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SMN 3005P

Made : Honda

Model : Vezel Hybrid 1.5RS Auto

Chassis No : RU31217689

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>horn</i>	1	\$ 840.60	\$ 745 840.60
2	Rear Bumper Side Retainer RH <i>men</i>	1	\$ 34.00	\$ + 34.00
3	Rear Bumper Side Retainer LH <i>men</i>	1	\$ 34.00	\$ + 34.00
4	Rear Bumper Reflector RH <i>men</i>	1	\$ 161.00	\$ + 161.00
5	Rear Bumper Reflector LH <i>men</i>	1	\$ 161.00	\$ + 161.00
6	Rear Bumper Side RH <i>horn</i>	1	\$ 217.60	\$ + 217.60
7	Rear Bumper Side LH <i>men</i>	1	\$ 217.60	\$ + 217.60
8	Rear Bumper Centre Lower Cover <i>men</i>	1	\$ 254.00	\$ + 254.00
9	Rear Bumper Lower Chrome Moulding <i>men</i>	1	\$ 122.30	\$ + 122.30
10	Rear Bumper Damper <i>men</i>	1	\$ 650.80	\$ + 650.80
11	Rear Tailgate <i>men</i>	1	\$ 1,393.40	\$ + 1,393.40
12	Rear Tailgate Lock Assembly <i>men</i>	1	\$ 187.40	\$ + 187.40
13	Rear Tailgate Lock Catch <i>men</i>	1	\$ 76.80	\$ + 76.80
14	Rear Tailgate Hinge RH <i>men</i>	1	\$ 55.00	\$ + 55.00
15	Rear Tailgate Hinge LH <i>men</i>	1	\$ 55.00	\$ + 55.00
16	Rear Tailgate Damper RH <i>men</i>	1	\$ 132.65	\$ + 132.65
17	Rear Tailgate Damper LH <i>men</i>	1	\$ 132.65	\$ + 132.65
18	Rear Tailgate Outer Garnish <i>men</i>	1	\$ 220.00	\$ + 220.00
19	Rear Emblem <i>men</i>	1	\$ 39.70	\$ + 39.70
20	Rear Tailgate "Vezel" Emblem <i>men</i>	1	\$ 58.00	\$ + 58.00
21	Rear Tailgate "Hybrid" Emblem <i>men</i>	1	\$ 66.20	\$ + 66.20
22	Rear Tailgate "RS" Emblem <i>men</i>	1	\$ 42.50	\$ + 42.50
23	Rear Tailgate Weatherstrip <i>men</i>	1	\$ 401.70	\$ + 401.70
24	Rear Tailgate Number Plate Lamp RH <i>men</i>	1	\$ 48.00	\$ + 48.00
25	Rear Tailgate Number Plate Lamp LH <i>men</i>	1	\$ 48.00	\$ + 48.00
26	Rear Tailgate Reflector Lamp RH <i>men</i>	1	\$ 389.20	\$ + 389.20
27	Rear Tailgate Reflector Lamp LH <i>men</i>	1	\$ 389.20	\$ + 389.20
28	Rear Tailgate Inner Handle <i>men</i>	1	\$ 46.00	\$ + 46.00
29	Rear Tailgate Inner Trim Board <i>men</i>	1	\$ 388.60	\$ + 388.60
30	Rear Tailgate Windscreen Moulding RH <i>men</i>	1	\$ 137.40	\$ + 137.40

31	Rear Tailgate Windscreen Moulding LH	1	\$	137.40	\$	+	137.40
32	Rear Tailgate Windscreen Moulding Lower	1	\$	81.70	\$	+	81.70
33	Rear Tailgate Wiper Motor	1	\$	512.00	\$	+	512.00
34	Rear Tailgate Stopper RH	1	\$	18.00	\$	+	18.00
35	Rear Tailgate Stopper LH	1	\$	18.00	\$	+	18.00
36	Rear End Panel	1	\$	857.20	\$	+	857.20
37	Rear End Panel Top Garnish	1	\$	135.00	\$	+	135.00
38	Rear Spare Tyre Panel	1	\$	1,108.80	\$	+	1,108.80
39	Rear Spare Tyre Panel Top Board	1	\$	168.00	\$	+	168.00
40	Rear Spare Tyre Panel Tools Box Sponge	1	\$	310.00	\$	+	310.00
41	Rear Taillamp Assembly RH	1	\$	502.40	\$	+	502.40
42	Rear Taillamp Lower Bracket RH	1	\$	32.60	\$	+	32.60
43	Rear Taillamp Assembly LH	1	\$	502.40	\$	+	502.40
44	Rear Taillamp Lower Bracket LH	1	\$	32.60	\$	+	32.60
45	Rear Fender RH	1	\$	1,054.00	\$	+	1,054.00
46	Rear Fender Wheel Arch Garnish RH	1	\$	235.00	\$	✓	235.00
47	Rear Fender Inner Trim Board RH	1	\$	548.00	\$	+	548.00
48	Rear Buzzer	1	\$	108.00	\$	+	108.00
49	Rear Smart Key Antenna Sensor	1	\$	182.40	\$	+	182.40
50	Rocker Panel Garnish RH	1	\$	387.30	\$	+	387.30
51	Rear Door RH	1	\$	923.40	\$	✓	923.40
52	Rear Door Upper Hinge RH	1	\$	38.50	\$	+	38.50
53	Rear Door Lower Hinge RH	1	\$	40.90	\$	+	40.90
54	Rear Door Outer Glass Moulding RH	1	\$	56.40	\$	+	56.40
55	Rear Door Lock RH	1	\$	241.30	\$	+	241.30
56	Rear Door Weatherstrip RH (Top)	1	\$	85.00	\$	+	85.00
57	Rear Door Weatherstrip RH (Lower)	1	\$	26.00	\$	+	26.00
58	Rear Door Glass Channel RH	1	\$	87.80	\$	+	87.80
59	Rear Door Glass Regulator with Motor RH	1	\$	378.00	\$	+	378.00
60	Rear Door Inner Trim Board RH	1	\$	650.00	\$	+	650.00
61	Rear Wheel Rim RH	1	\$	801.00	\$	450(SN)	801.00
62	Rear Wheel Hub Bearing RH	1	\$	314.00	\$	+	314.00
63	Rear Shock Absorber RH	1	\$	340.00	\$	+	340.00
64	Rear Axle Beam	1	\$	1,513.20	\$	+	1,513.20
65	Rear Exhaust Pipe Assembly	1	\$	821.00	\$	+	821.00
66	Rear Exhaust Pipe Assembly Heat Shield	1	\$	154.00	\$	+	154.00
67	Rear Exhaust Pipe Mounting	2	\$	55.00	\$	+	110.00
Parts Sub Total :					\$		20,511.60
20% Discount					\$		4,102.32
PARTS TOTAL :					\$		16,409.28

2121
1696.80

SN 450

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ 50.00

2	Rear Bumper Clips - Set	Nec	1	\$	50.00	\$	30 50.00
3	Rear Taillamp Clips - Set	2	1	\$	50.00	\$	+ 50.00
4	Rear Tailgate Reflector Lamp Clips - Set		1	\$	50.00	\$	+ 50.00
5	Rear End Panel Top Garnish Clips - Set		1	\$	50.00	\$	+ 50.00
6	Rear Fender Inner Shield Clips - Set		1	\$	80.00	\$	+ 80.00
7	Rear Fender Inner Trim Board Clips - Set		1	\$	100.00	\$	+ 100.00
8	Rear Door Inner Trim Board Clips - Set		1	\$	50.00	\$	+ 50.00
9	Rear Tailgate Sealant	NOP	1	\$	150.00	\$	+ 150.00
10	Rear End Panel Sealant	Nec	1	\$	150.00	\$	+ 150.00
11	Rear Spare Tyre Panel Sealant		1	\$	150.00	\$	+ 150.00
12	Rear Fender RH Sealant		1	\$	150.00	\$	+ 150.00
13	Rear Door RH Sealant		1	\$	150.00	\$	+ 150.00
14	Rear Tailgate Windscreen Glass Sealant		1	\$	150.00	\$	+ 150.00
15	Rear Tailgate Inner Trim Board Clips - Set		1	\$	50.00	\$	+ 50.00
16	Rear Tailgate Outer Garnish Clips - Set		1	\$	50.00	\$	+ 50.00
17	Rear Fender Wheel Arch Garnish Clips - Set	Nec	1	\$	100.00	\$	20 100.00
18	Rear Bumper Reverse Sensor - Set	2	1	\$	350.00	\$	+ 350.00
19	Rear Tailgate Reverse Camera	NOP	1	\$	500.00	\$	+ 500.00
20	Rear Bumper Top Mat - Aftermarket	Nec	1	\$	250.00	\$	+ 250.00
21	Rear Tyre RH		1	\$	400.00	\$	+ 400.00
						SPECIAL NETT TOTAL :	\$ 3,080.00

50

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 400 2,400.00
2	To Spray Paint Affected Areas	\$ 400 1,800.00
3	Wiring & Bulb Check	\$ + 100.00
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ + 150.00
5	To Transfer Rear Door RH Mechanism	\$ 60 150.00
6	To Transfer Tailgate Mechanism	\$ + 150.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ + 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 50 120.00
9	To Remove & Refix Rear Exhaust Pipe	\$ + 150.00
10	To Remove & Refix Fuel Tank	\$ + 250.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ + 150.00
12	To Remove & Refix Rear Undercarriage	\$ + 550.00
13	To Remove & Refix Rear Tyre and Conduct Wheel Balancing	\$ + 150.00
14	To Conduct Four Wheel Alignment	\$ 80 150.00
15	To apply anti rust on affected parts	\$ 30 150.00
16	To Conduct Water Leak Test	\$ + 100.00
17	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ + 480.00
		LABOUR TOTAL : \$ 7,150.00

1020

PARTS TOTAL : \$ 16,409.28
 SPECIAL NETT TOTAL : \$ 3,080.00
 LABOUR TOTAL : \$ 7,150.00
 GRAND TOTAL : \$ 26,639.28

Total = 3216.80

US \$ 2450 ✓

Adrian

n/s 29/08/24.

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/a. ... spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: