

A-Tec Motorz Pte Ltd  
 39 Woodlands Close,  
 Mega@Woodlands,  
 #02-43, Singapore 737856

28 Aug 2024

GBL7061R TOYOTA HIACE

| No                  | Qty | Parts Description                                       | Estimated<br>Parts Price  |
|---------------------|-----|---|---|
| 1                   | 1   | Rear windscreen moulding                                | \$ 140.80 <del>net</del>  |
| 2                   | 1   | Rear tailgate   | 1950 \$ 2,292.00 <del>66</del>                                  |
| 3                   | 2   | Rear tailgate dampers                                   | \$ 704.20 <del>X nn</del>                                       |
| 4                   | 1   | Rear tailgate inner trim board                          | \$ X 520.00 <del>X nn</del>                                     |
| 5                   | 1   | Rear tailgate lock                                      | 341.65 \$ 520.00 <del>dis</del>                                 |
| 6                   | 1   | Rear tailgate lock cover                                | \$ 130.00 <del>out</del>  |
| 7                   | 1   | Rear tailgate lock remote                               | \$ 850.00 <del>X nn</del>                                       |
| 8                   | 1   | Rear tailgate logo                                      | \$ 80.50 <del>net</del>   |
| 9                   | 1   | Rear tailgate outer garnish                             | 341 \$ 390.00 <del>cut</del>                                    |
| 10                  | 1   | Rear tailgate rubber                                    | 286 \$ 389.80 <del>cut</del>                                    |
| 11                  | 2   | Rear taillamps  | 475 \$ RHX <sup>nn</sup> 950.00 <del>LH car</del>               |
| 12                  | 2   | Rear taillamp lower garnishes e 9176.20 <del>each</del> | 352.40 <del>de</del> \$ RHX <del>568.40</del> <del>LH car</del> |
| 13                  | 1   | Rear end panel  | \$ X R 569.10 <del>X R</del>                                    |
| 14                  | 1   | Rear end panel inner member                             | \$ 624.50 <del>X nn</del>                                       |
| 15                  | 1   | Rear end panel top moulding                             | \$ 269.30 <del>X nn</del>                                       |
| 16                  | 1   | Rear bumper   | 550 \$ 858.00 <del>de</del>                                     |
| 17                  | 2   | Rear bumper top bracket                                 | \$ X 130.00 <del>X nn</del>                                     |
| 18                  | 2   | Rear bumper side retainers                              | 56.20 \$ RHX 112.40 <del>LH de</del>                            |
| 19                  | 1   | Rear step panel   | 288 \$ / BT 386.60 <del>BT</del>                                |
| 20                  | 1   | Rear windscreen sealant                                 | \$ 80.00 <del>net</del>   |
| 21                  | 1   | Rear tailgate "70KM/H" sticker                          | \$ 80.00 <del>net / 40</del>                                    |
| 22                  | 1   | Rear bumper clip (1 set)                                | \$ 25.00 <del>net</del>   |
| 23                  | 1   | Rear number plate                                       | \$ 50.00 <del>X nn</del>  |
| 24                  | 1   | Rear reverse sensor (1 set)                             | \$ 200 <del>90.00</del> <del>net</del>                          |
|                     |     |   | \$ 10,810.60  |
| Less 25%:           |     |   | \$ 2,702.65   |
| <b>Total Parts:</b> |     |   | <u>\$ 8,107.95</u>  |

5336.55  
 25% - 4002.41

| No                        | Labour Description  | Labour Charges                               |
|---------------------------|---|--|
| 1                         | 1 To remove, refit, replaced damaged lamps and check up rear electrical wiring  | \$ 80.00 <sup>40</sup>                       |
| 2                         | 1 To remove and refit inner garnishes, inner trim to assist repair.   | \$ 180.00 <sup>60</sup>                      |
| 3                         | 1 To transfer rear tailgate mechanism and wiring assembly to assist repair.   | \$ 120.00 <sup>60</sup>                      |
| 4                         | 1 To apply undercoating on repaired and replaced panel.   | \$ 200.00 <sup>50</sup>                      |
| 5                         | 1 To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld, re-align body structure and damaged consistent to the accident. | \$ 1,000.00 <sup>800</sup><br><del>700</del> |
| 6                         | 1 To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.   | \$ 1,000.00 <sup>750</sup><br><sup>800</sup> |
| <b>Total Labour:</b>      |   | <u>\$ 2,580.00</u> <sup>1810</sup>           |
| <b>Total Parts:</b>       |   | \$ 8,107.95                                  |
| <b>Total Labour:</b>      |   | \$ 2,580.00                                  |
| <b>Total repair cost:</b> |   | <u>\$ 10,687.95</u>                          |

Tanjuni 97495749 / 62523561  
 ip: 29/8/24 25 pm  
 tanjuni c/ikhandan  
 4/5 ready after repair  
 6-7 days.

| No | Supplementary Item                          | Labour Charges   |
|----|---|------------------|
| 1  | 2 Rear taillamp lower garnish retainer / BR | \$ 120.00        |
| 2  | 4 Rear step panel bracket / BT              | \$ 180.00        |
| 3  | 1 Rear tailgate handle X nn                 | \$ 243.80        |
| 4  | 1 Rear end panel lock X nn                  | \$ 536.60        |
|    |   | \$ 1,080.40      |
|    | Less 25%:                                   | \$ 270.10        |
|    | <b>Total Parts:</b>                         | <b>\$ 810.30</b> |

5. Tailgate panel LH - DN \$200

advertisement

6. Rear Fender sticker - MC \$300SN

25% 500  
375

4002.41  
1810  
375  
300  
6487.41  
- \$5200

7 days  
#

Steve (LKR)

30/8/24, 5:10pm