

A-Tec Motorz Pte Ltd
39 Woodlands Close,
Mega@Woodlands,
#02-43, Singapore 737856

GBL7061R TOYOTA HIACE

28 Aug 2024

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear windscreen moulding	\$ 140.80 acc
2	1	Rear tailgate	1950 \$ 2,292.00 bb
3	2	Rear tailgate dampers	\$ 704.20 X nn
4	1	Rear tailgate inner trim board	\$ X 520.00 X nn
5	1	Rear tailgate lock	341.65 \$ 520.00 dis
6	1	Rear tailgate lock cover	\$ 130.00 ant
7	1	Rear tailgate lock remote	\$ 850.00 X nn
8	1	Rear tailgate logo	\$ 80.50 acc
9	1	Rear tailgate outer garnish	341 \$ 390.00 cul
10	1	Rear tailgate rubber	286 \$ 389.80 cul
11	2	Rear taillamps	475 \$ RHX 950.00 LH cua
12	2	Rear taillamp lower garnishes e 9176-20 end	352.40 de \$ RHX 568.40 LH cua
13	1	Rear end panel	\$ X R 569.10 X R
14	1	Rear end panel inner member	\$ 624.50 X nn
15	1	Rear end panel top moulding	\$ 269.30 X nn
16	1	Rear bumper	550 \$ 858.00 de
17	2	Rear bumper top bracket	\$ X 130.00 X nn
18	2	Rear bumper side retainers	56.20 \$ RHX 112.40 LH de
19	1	Rear step panel	288 \$ / BT 386.60 71
20	1	Rear windscreen sealant	\$ 80.00 acc
21	1	Rear tailgate "70KM/H" sticker	\$ 80.00 acc / 40
22	1	Rear bumper clip (1 set)	\$ 25.00 acc
23	1	Rear number plate	\$ 50.00 X nn
24	1	Rear reverse sensor (1 set)	\$ 200 90.00 acc
			\$ 10,810.60
Less 25%:			\$ 2,702.65
Total Parts:			\$ 8,107.95

5336.55
25% - 4002.41

No	Labour Description	Labour Charges
1	1 To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00 40
2	1 To remove and refit inner garnishes, inner trim to assist repair.	\$ 180.00 60
3	1 To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 120.00 60
4	1 To apply undercoating on repaired and replaced panel.	\$ 200.00 50
5	1 To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld, re-align body structure and damaged consistent to the accident.	\$ 1,000.00 800
6	1 To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00 750
Total Labour:		\$ 2,580.00 1810
Total Parts:		\$ 8,107.95
Total Labour:		\$ 2,580.00
Total repair cost:		\$ 10,687.95

Tanjuni 97445749 / 62523561
 wpt 29/8/24 RES p
 tanjuni C/Wharton
 4/5 ready after repair
 6-7 days.

No	Supplementary Item	Labour Charges
1 2	Rear taillamp lower garnish retainer / BR	\$ 120.00
2 4	Rear step panel bracket / BT	\$ 180.00
3 1	Rear tailgate handle X nn	\$ 243.80
4 1	Rear end panel lock X nn	\$ 536.60
		\$ 1,080.40
	Less 25%:	\$ 270.10
	Total Parts:	\$ 810.30

5. Tailgate panel LH - DN \$200
advertisement

6. Rear Fender sticker / MC \$300 SN

25% 500
375

4002.41
1810
375
300
6487.41
+ \$5200
= 7 days
#

Steve (LKK)
30/8/24, 5:10pm