



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914	Ref: CS/AWA24080521/Tnp3e2 Date: 06/12/2024 Code: AWA
---	---

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 917U	Veh. Inspected	GBL 7061R
Policy No.	BVFCB0015202400	Coverage	0
Claim No.	CSG24VFC1A00012/SG	Excess	\$0.00
Assign From	HEW LEE FONG	Assign Date	29/08/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE 2.0 DX	C.C	1998
Engine No.	1TR2384503	Year of Reg.	15/02/2022
Chassis No.	TRH2005048630	Colour	RED
Odometer	111928 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15	APLUS	6
L/H Front Tyre	195 R15	APLUS	6
R/H Rear Tyre	195 R15	APLUS	6
L/H Rear Tyre	195 R15	APLUS	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/08/2024	Inspection Date	29/08/2024
Survey held at	A-TEC AUTOMOTIVE PTE LTD - 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days