

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0035591
Wong Kaijie, Allan (Huang Kaijie,
Allan)

Page : 1 of 1
Your ref. : TP-SLB 8863X ECICS
Job No. : 74676
Our ref. : 24.08.36
Payment :
Date : 27/8/2024

Attn :

Vehicle No : SMA 7193X
Vehicle Model : Toyota C-HR
Accident on : 27/8/2024

NOT Resurvey
Resurvey B4 paint

8256893

4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front door LH	1,674.50	25.00	1,255.88
1.00	Set	Front door frame tapes LH (outside)	130.80	25.00	98.10
1.00	Pc	Front door protector LH lower photo	430.60	25.00	322.95
Labour & Misc:					
1.00		To knock dents on rear door LH+renew parts	400.00		400.00
1.00		To spray paint (including accessory-door mouldings red)	600.00		600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sub-Total
GST 9.00%
Total

2,676.93
240.92
S\$ 2,917.85

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No : EST0035591
Wong Kaijie, Allan (Huang Kaijie,
Allan)

Page : 1 of 1
Your ref : TP-SLB 8863X ECICS
Job No : 74676
Our ref : 24.08.36
Payment :
Date : 19/9/2024

Attn :

Vehicle No : SMA 7193X
Vehicle Model : Toyota C-HR
Accident on : 27/8/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
SUPPLEMENTARY:					
Labour & Misc:					
1.00		To remove+refix front fender arch LH	30.00		30.00 X
1.00		To knock dents on front fender LH	50.00		50.00 X
1.00		To spray paint	200.00		200.00 X

Sub-Total 280.00
GST 9.00% 25.20
Total S\$ 305.20

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."