



Your Ref : Z24VC05022681

Date: 06th Sep 2024

Our Ref : CS/LPC24080524/Jnh3e2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YP 1982D
ACCIDENT ON 29/08/2024**

Instruction was received to inspect the vehicle Reg. No. YP 1982D. The inspection was conducted on 30/08/2024 at the premises of M/s Kim Soon Lee Pte Ltd, 200 Bedok South Avenue 1, Singapore 469331.

The following vehicle information was recorded:

Registration Number	: YP 1982D
Make/Model	: Hino GH8JRMA-QGS
Year of Registration	: 2016
Body Colour	: White
Chassis Number	: GH8JRM10297
Engine Capacity	: 7684 cc
Speedometer Reading	: Not Available

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 30,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,564.00)
Nett Liability	<u>S\$ 25,436.00</u> =====

Vehicle Inspected By:



ELTON SEET BOON KIAT
Asst. Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.