



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD
51 CLUB STREET, #03-00
LIBERTY HOUSE SINGAPORE 069428

Ref: CS/LIP24060136/Uvh3

Date: 19/06/2024

Code: LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PD 28K	Veh. Inspected	SNJ 8784A
Policy No.	-	Coverage	0
Claim No.	AVS24/1732	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	19/06/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA HYBRID (A)	C.C	1496
Engine No.	1NZ8371871	Year of Reg.	29/12/2017
Chassis No.	NHP1707107938	Colour	WHITE
Odometer	138772 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/60R15	HANKOOK	6
L/H Front Tyre	195/60R15	HANKOOK	6
R/H Rear Tyre	195/60R15	FALKEN	6
L/H Rear Tyre	195/60R15	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/05/2024	Inspection Date	19/06/2024
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days