



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

2 September 2024

REG NO.: SNB 9982 E
MAKE/MODEL: HYUNDAI AVANTE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear boot lid	\$ 11 2,050.00 X
2	Rear boot hinges	\$ 11 302.50 X
1	Rear boot inner trim	\$ 11 499.41 X
1	Rear boot lamp	\$ 11 1,025.88 X
1	Rear boot logo base with lock switch	\$ 11 355.75 X
1	Rear boot outer garnish	\$ 11 488.65 X
1	Rear boot rubber	\$ 11 265.65 X
1	Rear boot "S" emblem	\$ 11 77.65 X
1	Rear boot "AVANTE" emblem	\$ 11 97.90 X
2	Rear taillamps	\$ 11 1,754.00 X
1	Rear end panel	\$ 11 999.89 X
1	Rear end panel inner garnish	\$ 11 200.11 X
1	Rear bumper	\$ 11 777.65 X
2	Rear bumper side brackets	\$ 11 181.94 X
1	Rear bumper lower brake lamp	\$ 11 199.74 X
1	Rear bumper lower lid spoiler	\$ 11 340.65 X
2	Rear bumper reflectors	\$ 11 222.44 X
1	Rear bumper reinforcement	\$ 11 399.54 X
2	Rear bumper reinforcement stays	\$ 11 158.00 X
3	Rear bumper reinforcement lower brackets	\$ 11 84.00 X
4	Rear bumper PDC sensors	\$ 11 846.16 X
2	Rear bumper side retainers	\$ 11 135.28 X
(202)		\$ 11,462.79
Less 10%		\$ 1,146.28
		\$ 10,316.51

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$ 11 80.00 50 S/N
1	Rear licence plate	\$ 11 80.00 40 S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 11 180.00 X
3	To remove and refit rear reverse sensor.	\$ 150.00 30
4	To transfer boot lid mechanism and wiring assembly.	\$ 11 80.00 X
5	To apply undercoating.	\$ 11 150.00 X
6	Panel beating.	\$ 1,800.00 530
7	To re-spray painting on the affected areas.	\$ 1,600.00 600
		\$ 4,040.00

P-1514.73
202
12/1.78
90
1200

total 14516.51