



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

2 September 2024

REG NO.: SLJ 9349 R
MAKE/MODEL: MAZDA CX8

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>LIST ITEMS</u>		
1	Rear windscreen inner seal	\$ 110.00 ✓
1	Rear tailgate	\$ 1,452.30 ✓
1	Rear tailgate inner board	\$ 447.94 X
2	Rear tailgate lamps	\$ 1,500.00 X
1	Rear tailgate lock	\$ 197.11 X
1	Rear tailgate logo	\$ 87.92 ✓
1	Rear tailgate rubber	\$ 199.70 X
1	Rear tailgate "CX-8" emblem	\$ 82.47 ✓
2	Rear taillamps	\$ 1,707.79 X
1	Rear end panel	\$ 866.15 X
1	Rear end panel inner garnish	\$ 116.52 X
1	Rear bumper	\$ 1,494.00 ✓
2	Rear bumper brackets	\$ 30.73 ✓
1	Rear bumper inner sponge	\$ 36.54 X
2	Rear bumper reflectors	\$ 295.11 X
1	Rear bumper reinforcement	\$ 439.35 ✓
2	Rear bumper side brackets	\$ 142.54 X
2	Rear bumper side retainers	\$ 178.81 X
1	Rear spare tyre top board	\$ 380.67 X
202		\$ 9,765.65
Less 10%		\$ 976.56
		\$ 8,789.08
<u>SPECIAL NETT ITEMS</u>		
1	Rear windscreen sealant	\$ 80.00 40
1	Rear bumper clip (1 set)	\$ 80.00 40
1	Rear number plate with holder	\$ 50.00 X
1	Rear reverse sensor (1 set)	\$ 480.00 X
		\$ 690.00

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	X
3	To remove and refit rear reverse sensor.	\$	150.00	30
4	To transfer rear tailgate mechanism and wiring assembly.	\$	80.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	120
6	To apply undercoating.	\$	200.00	30
7	Panel beating.	\$	1,600.00	550
8	To re-spray painting on the affected areas.	\$	1,500.00	600
		\$	3,970.00	

GRAND TOTAL :**\$ 13,449.08**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 345787
202
2766.30
80
1410
4256.30
20%
3405